

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOMO	OTIVE SERVICES PTE LTD		Ref:	CS/SMR22011640/Gqy3m4	
	60 WOODLANDS I E4SINGAPORE 75	INDUSTRIAL PARK 57705		Date:	30/01/2023	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHD 6146H	Veh. Inspected		SHD 1465U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/11/22/2037	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		18/11/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	HYUNDAI I30 GDH 1.6	c.c		1582	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	TMAD281UVHJ141704	Colour		SILVER	
	Odometer	551902 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65R15	HANKOOK		6 mm	
	L/H Front Tyre	195/65R15	HANKOOK		6 mm	
	R/H Rear Tyre	195/65R15	HANKOOK		6 mm	
	L/H Rear Tyre	195/65R15	HANKOOK		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE D	DAMAGES SEE DETAILS.				
5.	General Information					
	Accident Date	16/11/2022	Inspection Dat	е	21/11/2022	
	Survey held at PREMIER AUTOMOTIVE SERVICES PTE LTD					
	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443					
5a.	Remarks					
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		5 Work	ing Days	