



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22011648/Aqy3e2 Date: 28/02/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDY 3781E	Veh. Inspected	SGY 8346K	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS22/2000	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	18/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	MR053ZEC107153038	Colour	SILVER	
Odometer	238065 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	YOKOHAMA	6 mm	
L/H Front Tyre	185/70 R14	YOKOHAMA	6 mm	
R/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm	
L/H Rear Tyre	185/70 R14	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2022	Inspection Date	21/11/2022	
Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701			
5a. Remarks				
A)REGISTRATION DATE: 10 OCT 2007 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	