

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

TP A16.

Xiao Tony

15-Nov-22

Our ref : TP/5189/22

Khor Liang Yeak

RE : estimate cost for vehicle no : SMZ 6527S

1 pc	tailgate	Repair	\$	1,680.00	+
1 pc	tailgate lock	new		427.00	+
1 pc	Paize emblem	for		49.56	-
1 pc	logo emblem	for		72.20	✓
2 pcs	tailgate reflector	new		602.80	+
1 pc	tailgate w/strip	int		325.10	2
2 pcs	taillamp	new		1,348.00	+
1 pc	rear bumper	Delhd		947.20	✓
1 pc	rear bumper lower spoiler	Delhd		353.40	✓
2 pcs	rear bumper reflector	new		251.00	+
2 pcs	rear bumper garnish	LH TORN	3201.66	312.00	156
2 pcs	reverse sensor	new		490.80	✓
2 pcs	rear bumper retainers	new	2401.24	95.40	✓
14 pcs	rear bumper clips	new		77.00	30
1 pc	rear no plate lamp	new		173.80	+
1 pc	end panel	Delhd		525.00	✓
1 pc	end panel inner garnish	Delhd		157.00	✓

less 25%

1 pc	rear no plate	sent	90	40.00	snett	✓
1 pc	rear w/screen gum	new		50.00		✓
Panel beating.				1,000.00	60	✓
Spray painting.			1470	1,000.00	60	✓
Wiring.				30.00		✓
Rust proofing.				80.00	60	✓
Remove & refit rear w/screen.				120.00		✓
Transfer tailgate fitting.				80.00	60	✓

8,315.45

582.08

8,897.53

LKK Auto Consultants hence notify Plus 7% GST

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DSD : eight thousand eight hundred ninety-seven & cents fifty-three only.

Adrian G
L/S 16/11/22
DS Pay

total: 3961.24

L/S: 3.1K