

Date: 18/11/2022

Vehicle No: SNF5659U

Model: HYUNDAI KONA HEV 1.6 DCT

Chassis: KMHK281EVNU094093-2022

Reg.Year: 2022

Third Party Insurer: CHINA TAIPING

Third Party Veh No: XE4457D

Date of Accident: 16/11/2022

Estimator: TING AN

Surveyor:

Not Authored
Repair After Pain
3days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR PROTECTOR COVER RH	1		<i>Re</i> \$85.00
2	REAR FENDER WHEEL ARCH GARNISH COVER RH	1		<i>Re</i> \$85.00
3	REAR FOG LAMP RH	1		<i>Re</i> \$531.00
4	REAR RIM RH	1		<i>Re</i> \$880.00
5	REAR ABSORBER RH	1		\$405.00
6	REAR KNUCKLE ARM RH	1		\$436.00
7	REAR WHEEL BEARING HUB RH	1		\$394.00
8	REAR BUMPER	1		<i>Re/Div</i> \$1,558.00
9	REAR BUMPER SIDE BRACKET RH	1		<i>Re</i> \$54.00
10	REAR DOOR RH	1		REPAIR
11	REAR FENDER RH	1		REPAIR
SUB TOTAL				\$4,428.00
LESS 20%				-\$885.60
PARTS TOTAL				\$3,542.40

✓
✓
X
✓
?
?
?
✓
X
✓
?

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR FENDER WHEEL ARCH GARNISH COVER CLIPS	1		<i>Re</i> \$50.00
2	REAR DOOR PROTECTOR COVER CLIPS	1		<i>Re</i> \$40.00
3	REAR BUMPER CLIPS	1		<i>Re</i> \$50.00
4	REAR TYRE RH	1		\$250.00
S/N TOTAL				\$390.00

✓
✓
✓
?

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

30d
\$500.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR FENDER RH & ETC.

\$500.00 *?*

LABOUR CHARGES TO REMOVE & REPLACE REAR RIM RH & ETC.

\$120.00 *2d*

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18/11/2022
Vehicle No: SNF5659U
Model: HYUNDAI KONA HEV 1.6 DCT
Chassis: KMHK281EVNU094093-2022
Reg.Year: 2022

Third Party Insurer: CHINA TAIPING
Third Party Veh No: XE4457D
Date of Accident: 16/11/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE REAR ABSORBER RH, REAR KNUCKLE RH,
REAR WHEEL BEARING RH & ETC.

\$300.00 7

TO WHEEL ALIGNMENT & BALANCING.

\$80.00 201

LABOUR TOTAL \$1,500.00

TING AN

TOTAL

\$5,432.40

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1903

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

