



Tax Invoice

Tesla Motors Singapore Private Limited

Lorong 8 Toa Payoh
319254 Singapore , SG
201010405N
www.tesla.com

Invoice Number 2040R0000000622
Invoice date 2022/11/28
Reference Number EPC-1897481
Customer Number 3610424

Sold To

Optima Werkz
10 Ang Mo Kio
Industrial Park 2A, 01-05
Singapore, SG 568047
SG
victor.seng@ow.sg

Delivery Address

Optima Werkz
Fun Siong Seng
10 Ang Mo Kio
Industrial Park 2A, 01-05
Singapore, SG 568047
SG

Vehicle Identification Number

LRW3F7EL6MC283030

Payment Terms

Net Due in 30 days

PO Number

OD#617 - SNB8157C

Article	Description	Quantity	Unit Price	Discount	Total
1104669-CN-G	M3S BUMPER BEAM FOAM, CHN	1	46.73	(14.02)	46.73
2567961-03-C	ASY,HARN,FEM HARNESS,CONTI ARS CAPPED	1	93.46	(28.04)	93.46
1085927-00-C	GRILLE ASSEMBLY, FRONT FASCIA LOWER, M3	1	102.80	(30.84)	102.80
1108647-00-H	RADAR, SEVEN PIN PERPENDICULAR	1	345.79	(103.74)	345.79
1081401-EC-D	FENDER ASSY LH MODEL 3 E- COATED	1	448.60	(134.58)	448.60
1453378-00-A	M3 ECE Headlamp Fascia Bracket (RH)	1	7.48	(2.24)	7.48
1088149-00-F	M3S ASY - CRUSH CAN RH	1	52.34	(15.70)	52.34
1110240-00-B	COMP, FR END CARRIER, M3	1	738.32	(221.50)	738.32
1519965-S0-A	M3 FR FASCIA SVC-CN, UNPAINTED	1	766.00	(229.80)	766.00
1084170-00-B	REINF - FASCIA FRT CTR UPR TO FEM RH, M3	1	7.48	(2.24)	7.48
1559787-00-A	M3 ACTIVE GRILLE SHUTTER ASSY, HEAT PUMP	1	186.92	(56.07)	186.92
1077395-00-D	LAMP ASY, FASCIA LAMP, ECE UP-LEVEL, LH	1	271.03	(81.31)	271.03
1084172-00-F	BRKT ASM - FASCIA FRT CTR TO FDR RH, M3	1	12.15	(3.64)	12.15

Article	Description	Quantity	Unit Price	Discount	Total
1514952-00-C	HD/LP ASY, GLOBAL, LH	1	1,741.00	(522.30)	1,741.00
1088148-00-F	M3S ASY - CRUSH CAN LH	1	52.34	(15.70)	52.34
1103760-00-C	FEM RADAR BRKT	1	7.48	(2.24)	7.48
1090492-00-B	M3, SEALS, Hood, Frunk	1	46.73	(14.02)	46.73
2067958-00-B	ASY,HARN,FR FASCIA.M3,FASCIA LAMPS	1	88.78	(26.64)	88.78
1098489-00-E	M3 FRONT T BADGE, EF	1	48.60	(14.58)	48.60
1453377-00-A	M3 ECE Headlamp Fascia Bracket (LH)	1	7.48	(2.24)	7.48
1104667-CN-L	M3S ASY, FR BUMPER BEAM - EXTRUSION, CHN	1	271.03	(81.31)	271.03
1645350-00-A	ASY, FRUNK, MODEL 3 AH	1	64.49	(19.35)	64.49
1088437-00-A	S2 PA RETAINER, FRT FASCIA, M3	1	4.67	(1.40)	4.67
1524888-00-A	M3 WSHLD ASSY RHD IR ACOUSTIC	1	763.00	(228.90)	763.00
1084169-00-B	REINF - FASCIA FRT CTR UPR TO FEM LH, M3	1	7.48	(2.24)	7.48
1077396-00-D	LAMP ASY, FASCIA LAMP, ECE UP-LEVEL, RH	1	271.03	(81.31)	271.03
1084171-00-F	BRKT ASM - FASCIA FRT CTR FDR LH, M3	1	12.15	(3.64)	12.15
1108648-00-E	BRACKET, MODEL3 RADAR Y160	1	4.67	(1.40)	4.67
1643845-00-A	M3 ACTIVE HOOD HINGE, LH	1	74.77	(22.43)	74.77
1081582-00-E	1081582-00-E	1	116.82	(35.05)	116.82
1607808-00-A	COOLING FAN MODULE ASY	1	663.55	(199.07)	663.55
1607811-00-A	RADIATOR, COOLING FAN MODULE ASY	1	79.44	(23.83)	79.44
1500398-00-H	ACTUATOR AND CABLE ASSEMBLY, HOOD LATCH	1	107.48	(32.24)	107.48
1096834-00-A	M3 FR LICENSE PLATE BRACKET EU	1	29.91	(8.97)	29.91
1643846-00-A	M3 ACTIVE HOOD HINGE, RH	1	74.77	(22.43)	74.77
1514953-00-C	HD/LP ASY, GLOBAL, RH	1	1,308.41	(392.52)	1,308.41
1127503-11-D	USS UPA RADIAL, DCR, ASSY, PEARL WHITE	4	163.55	(196.26)	654.21
1088438-00-A	S3 PA RETAINER, FRT FASCIA, M3	1	4.67	(1.40)	4.67
1084182-00-E	BRACKET - FASCIA SIDE TO FDR RH, M3	1	1.87	(0.56)	1.87
1607807-00-A	FAN AND SHROUD, COOLING FAN MODULE ASY	1	84.11	(25.23)	84.11
1500397-00-E	HOOD LATCH DOUBLE PULL SINGLE ACTUATOR	1	177.57	(53.27)	177.57
1081400-EC-D	FENDER ASSY RH MODEL 3 E-COATED	1	448.60	(134.58)	448.60

Article	Description	Quantity	Unit Price	Discount	Total
1081390-EC-C	HOOD ASSY MODEL 3	1	663.55	(199.07)	663.55
1084181-00-E	BRACKET - FASCIA SIDE TO FDR LH, M3	1	1.87	(0.56)	1.87

Subtotal

10,961.59



Tax Invoice

Tesla Motors Singapore Private Limited

Lorong 8 Toa Payoh
319254 Singapore, SG
201010405N
www.tesla.com

Invoice Number 2040R0000000637
Invoice date 2022/12/08
Reference Number EPC-1897481
Customer Number 3610424

Sold To

Optima Werkz
10 Ang Mo Kio
Industrial Park 2A, 01-05
Singapore, SG 568047
SG
victor.seng@ow.sg

Delivery Address

Optima Werkz
Fun Siong Seng
10 Ang Mo Kio
Industrial Park 2A, 01-05
Singapore, SG 568047
SG

Vehicle Identification Number	Payment Terms	PO Number
LRW3F7EL6MC283030	Net Due in 30 days	OD#617 - SNB8157C

Article	Description	Quantity	Unit Price	Discount	Total
1090160-S0-B	M3 ASSY FENDER SUPPORT RH	1	22.43	(6.73)	22.43 ✓
1088439-00-A	S4 PA RETAINER, FRT FASCIA, M3	1	4.67	(1.40)	4.67 ✓
1104777-00-A	ASY-M3 FRUNK REINFORCEMENT	1	13.08	(3.93)	13.08 ✓
1645989-00-A	M3 ACTIVE HOOD STRUT	2	52.34	(31.40)	104.67 ✓
1645352-00-A	FRUNK CORNER BRACKET, LH, MODEL 3 AH	1	2.40	(0.72)	2.40 ✓
1090159-S0-B	M3 ASSY FENDER SUPPORT LH	1	22.43	(6.73)	22.43 ✓
1088440-00-A	S5 PA RETAINER, FRT FASCIA, M3	1	4.67	(1.40)	4.67 ✓
1645986-00-A	M3 ACTIVE HOOD STRIKER INSTALL	1	2.80	(0.84)	2.80 ✓

Subtotal

177.17



Tax Invoice

Tesla Motors Singapore Private Limited

Lorong 8 Toa Payoh
319254 Singapore, SG
201010405N
www.tesla.com

Invoice Number 2040R0000000630
Invoice date 2022/12/06
Reference Number EPC-1897481
Customer Number 3610424

Sold To

Optima Werkz
10 Ang Mo Kio
Industrial Park 2A, 01-05
Singapore, SG 568047
SG
victor.seng@ow.sg

Delivery Address

Optima Werkz
Fun Siong Seng
10 Ang Mo Kio
Industrial Park 2A, 01-05
Singapore, SG 568047
SG

Vehicle Identification Number	Payment Terms	PO Number
LRW3F7EL6MC283030	Net Due in 30 days	OD#617 - SNB8157C

Article	Description	Quantity	Unit Price	Discount	Total
1120111-00-A	Asy, Battery Backed Siren, M3	1	44.86	(13.46)	44.86

Subtotal 44.86

Code	Taxable total (SGD)	GST (%)	Total GST (SGD)



Tesla Motors
 17 Lor 8 Toa Payoh
 Singapore, SG, 319254
 Tax no:

Tax Invoice

SERVICE DEPARTMENT HOURS
 Mon-Fri: 8:00 a.m. - 6:00 p.m
 Saturday-Sunday: Sat-Sun: Closed

Invoice date	Invoice number
06-Feb-2023	2040S0000005473
Date/Time Received	Date/Time Promised
02-Feb-2023 10:52:01	03-Feb-2023 03:00:08
Odometer In	Odometer Out
19046 Kilometers	19046 Kilometers
Ready Date	
02-Feb-2023 04:58:33	
Service Advisor	
Sinna Maricar	

Bill To	Mobile Phone	Additional Phone	Vehicle Identification Number
Lee Zhen Hui Zenden 120 Serangoon North Avenue 1 Singapore, 550120 Singapore victor.seng@ow.sg	+6583189973		LRW3F7EL6MC283030
	Year	Model	License Plate Number
	2021	MODEL 3	SNB8157C
			Colour
			Pearl White Multi-Coat

Job Number	Description Of Work	Amount (SGD)																								
1	<p>Concern: Update Vehicle Firmware To Correct Track Mode Speedometer</p> <p>Inspected Vehicle Firmware Version. Tested okay, No Update Necessary</p> <p>Correction: Inspect Vehicle Firmware Version; No Update Necessary</p> <p style="text-align: right;">Pay Type: Basic Vehicle Limited Warranty</p>	0.00																								
2	<p>Concern: Install O-ring On Trunk Power Strut</p> <p>Installed O-ring On Trunk Power Strut as required.</p> <p>Correction: Install Or Replace O-Ring On Trunk Power Strut</p> <p>Parts Replaced or Added</p> <table border="1" style="width: 100%;"> <thead> <tr> <th>Part</th> <th>Quantity</th> </tr> </thead> <tbody> <tr> <td>O-RING, EPDM, M3 POWER STRUT(1831785-00-A)</td> <td style="text-align: center;">1.0</td> </tr> </tbody> </table> <p style="text-align: right;">Pay Type: Basic Vehicle Limited Warranty</p>	Part	Quantity	O-RING, EPDM, M3 POWER STRUT(1831785-00-A)	1.0	0.00																				
Part	Quantity																									
O-RING, EPDM, M3 POWER STRUT(1831785-00-A)	1.0																									
3	<p>Concern: Heavy Pump Noise</p> <p>Carried out testing on site. Unable to verify specific concern. During testing found the A/C system does not function correctly. Vehicle failed thermal performance tests and failed HVAC performance tests. Performed Vacuum air bleed/refill of the coolant system. Carried out recovery A/C recovery and recharge procedure. Not enough refrigerant present. 660 grams recovered, specification is 1000grams to 1040grams. Recharged A/C system as required. Carried out HVAC and thermal performance tests. Tested okay.</p> <table border="1" style="width: 100%;"> <thead> <tr> <th>Correction: A/C Refrigerant (Recovery & Recharge)</th> <th>Price</th> <th>Adjustment</th> <th>Subtotal</th> </tr> </thead> <tbody> <tr> <td></td> <td style="text-align: right;">270.00</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">270.00</td> </tr> <tr> <th>Correction: Cooling System (Heat Pump) (Vacuum Refill)</th> <th>Price</th> <th>Adjustment</th> <th>Subtotal</th> </tr> <tr> <td></td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">0.00</td> </tr> <tr> <th>Correction: General Diagnosis</th> <th>Price</th> <th>Adjustment</th> <th>Subtotal</th> </tr> <tr> <td></td> <td style="text-align: right;">100.00</td> <td style="text-align: right;">0.00</td> <td style="text-align: right;">100.00</td> </tr> </tbody> </table> <p style="text-align: right;">Pay Type: Customer Pay</p> <p>Total Labour Amount 370.00</p>	Correction: A/C Refrigerant (Recovery & Recharge)	Price	Adjustment	Subtotal		270.00	0.00	270.00	Correction: Cooling System (Heat Pump) (Vacuum Refill)	Price	Adjustment	Subtotal		0.00	0.00	0.00	Correction: General Diagnosis	Price	Adjustment	Subtotal		100.00	0.00	100.00	370.00
Correction: A/C Refrigerant (Recovery & Recharge)	Price	Adjustment	Subtotal																							
	270.00	0.00	270.00																							
Correction: Cooling System (Heat Pump) (Vacuum Refill)	Price	Adjustment	Subtotal																							
	0.00	0.00	0.00																							
Correction: General Diagnosis	Price	Adjustment	Subtotal																							
	100.00	0.00	100.00																							

Service Centre hourly rate: SGD 186.92.