



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: JULIANA LEE			Ref: CS3/INC22000342/Gqy3e2-1 Date: 23/11/2022 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBQ 5675G	Veh. Inspected	SJB 686S	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1157637-001	Excess (\$)	0.00	
Assign From		Assign Date	09/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN TOUAREG 3.6	c.c	3597	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	WVGZZZ7PZBD027263	Colour	WHITE	
Odometer	180568 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/55 R18	CONTINENTAL	6 mm	
L/H Front Tyre	255/55 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	255/55 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	255/55 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/01/2022	Inspection Date	11/01/2022	
Survey held at	ECO AUTOMOBILE CLAIMS & REPAIR PTE LTD 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417808			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	