



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept		S1000005 / ICFIC1	M/S Grab Rentals Pte Ltd				
		Document No. 0	3 Media Close #01-03/06 Singapore 138498				
		Document Date 17/11/2022	Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0362C	0	18674	75/DS/SLU0362C
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU003576006		2ZRS111198	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:XE4777E ACC DATE:17/11/22 DRIVE IN:17/11/22 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30 / 102.00	
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST				198.00	
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
4	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				198.00	
5	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA				792 / 3188.00	
6	B	BP-RES2 RESPRAY ACC AFF AREA				656 / 2624.00	
7	1	U52159-47913 COVER, RR BUMPER	1.00	478.90		478.90	
8	2	U52575-47040 RETAINER, RR BUMPER	1.00	127.40		127.40	
9	3	U52576-47040 RETAINER, RR BUMPER	1.00	126.10		126.10	
10	4	U52023-47030 REINFORCEMENT	1.00	360.10		360.10	
11	5	U52453-47030 GUARD, RR BUMPER	1.00	506.20		506.20	
12	6	U52565-47900 FILLER, RR BUMPER	1.00	133.60		133.60	
13	7	U52161-16010 PIECE, RR BUMPER	10.00	4.80		48.00	
14	8	U81551-47283 LENS & BODY, RR	1.00	489.00		489.00	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others		Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept				S1000005 / ICFIC1		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
				Document No. 0					
				Document Date 17/11/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0362C	0	18674	75/DS/SLU0362C		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKB3FU003576006		2ZRS111198	60	Ng Mei Yen	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
15	9	U81497-47020 COVER, RR <i>see</i>				1.00	69.90		69.90
16	0	U81581-47011 LENS & BODY, RR <i>ca</i>				1.00	544.40		544.40
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____ <i>Rasmi</i> <i>Hp 90010068</i> <i>3 days</i> <i>18/11/22 @ 1520</i> <i>Resy before part.</i>									
For & on behalf of		Customer's Signature		Charge Summary			Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts 2,883.60 Labour 6,486.00 Sublet 0.00 Lubrication/Fluid 0.00 Others 0.00			9,369.60 GST 7.00% 655.87 Less 0.00 Amount Due 10,025.47		