

Huey Yon (LKKAuto)


**From:** Simon Ho (LKKAuto)  
**Sent:** Friday, 16 December 2022 12:05 PM  
**To:** Huey Yon (LKKAuto)  
**Subject:** Re: FCI-TP SLU 362C-SURVEY BY Rasul (CS/FCI22011698/Rny3)

Dear Huey Yon,

Audit check done for SLU362C without problem.

Best Regards,

**Simon Ho**  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561| email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Huey Yon (LKKAuto) <hueyyon@lkkauto.com>  
**Sent:** Friday, 16 December 2022 11:19 am  
**To:** Simon Ho (LKKAuto) <SimonHo@lkkauto.com>  
**Subject:** FCI-TP SLU 362C-SURVEY BY Rasul (CS/FCI22011698/Rny3)

Dear Simon,

For your Re-audit.

Best Regards,

**Huey Yon** | case handler  
**LKK Auto Consultants Pte.Ltd.**  
Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

---

**From:** Simon Ho (LKKAuto) <SimonHo@lkkauto.com>  
**Sent:** Tuesday, 22 November 2022 2:33 PM  
**To:** Huey Yon (LKKAuto) <hueyyon@lkkauto.com>  
**Subject:** Re: FCI-TP SLU 362C-SURVEY BY Rasul (CS/FCI22011698/Rny3)

Dear Huey Yon,

Audit check done for SLU362C, found no photo upload.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561| email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Huey Yon (LKKAuto) <[hueyyon@lkkauto.com](mailto:hueyyon@lkkauto.com)>  
**Sent:** Tuesday, 22 November 2022 2:14 pm  
**To:** Simon Ho (LKKAuto) <[SimonHo@lkkauto.com](mailto:SimonHo@lkkauto.com)>  
**Subject:** FCI-TP SLU 362C-SURVEY BY Rasul (CS/FCI22011698/Rny3)

Dear Simon,

For your audit.

Best Regards,

**Huey Yon** | Reports  
**LKK Auto Consultants Pte.Ltd.**  
Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: [report@lkkauto.com](mailto:report@lkkauto.com)  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933