



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:WINNIE		Ref: CC4/ASM22011705/Upa3q2 Date: 18/05/2023 Code: HSB	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	PZ 7200S	Veh. Inspected	GBL 7870Y
Policy No.	GA572716	Coverage (\$)	0.00
Claim No.	S2M04F8J	Excess (\$)	0.00
Assign From		Assign Date	22/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN NV200 (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JN1YAAM20Z0001811	Colour	WHITE
Odometer	15840 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	165/80 R14	TOYO	7 mm
L/H Front Tyre	165/80 R14	TOYO	7 mm
R/H Rear Tyre	165/80 R14	TOYO	7 mm
L/H Rear Tyre	165/80 R14	TOYO	7 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & REAR WINDSCREEN SHATTERED. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	21/11/2022	Inspection Date	22/11/2022
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	