



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)			Ref:	CS/SPF22011726/Twy3e2
ACCIDENT CLAIMS SECTION(SPORE POLICE FORCE)POLICE LOGISTICS BASE (PLB)1 HEMMANT ROADSINGAPORE 438675			Date:	01/02/2023
ATTN: HAFIZUL FARHAN			Code:	SPF
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 548J	Veh. Inspected	SND 5974U	
Policy No.		Coverage (\$)	0.00	
Claim No.	ACS/105/009/2022/071	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN	Assign Date	22/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN KICKS	c.c	1198	
Engine No.	HIDDEN	Year of Reg.	2022	
Chassis No.	MNTFEAP15Z0005328	Colour	GREY	
Odometer	14426 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R17	DUNLOP	6 mm	
L/H Front Tyre	205/55 R17	DUNLOP	6 mm	
R/H Rear Tyre	205/55 R17	DUNLOP	6 mm	
L/H Rear Tyre	205/55 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2022	Inspection Date	24/11/2022	
Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	