

## Xin Yu (LKK Auto)

---

**From:** Xin Yu (LKK Auto)  
**Sent:** Monday, February 6, 2023 2:14 PM  
**To:** Elaine Kuan (LKK Auto); Hafizul Farhan RAHMAT (SPF)  
**Cc:** Cui Fen ENG (SPF); SUR  
**Subject:** RE: Survey Report & Invoice of Vehicle SND 5974U Ref: ACS/105/009/2022/071  
**Attachments:** SND 5974U LKKAdjustment.pdf

Dear Hafizul,

Enclosed herewith the Amended report.

Sorry for any inconvenience caused.

Thanks and Best Regards,

**Xin Yu** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | fax: 6256-4315 | email: [xinyu@lkkauto.com](mailto:xinyu@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Elaine Kuan (LKK Auto) <elainekuan@lkkauto.com>  
**Sent:** Friday, February 3, 2023 11:51 AM  
**To:** Hafizul Farhan RAHMAT (SPF) <Hafizul\_Farhan\_RAHMAT@spf.gov.sg>; Xin Yu (LKK Auto) <xinyu@lkkauto.com>  
**Cc:** Cui Fen ENG (SPF) <ENG\_Cui\_Fen@spf.gov.sg>; SUR <sur@lkkauto.com>  
**Subject:** Re: Survey Report & Invoice of Vehicle SND 5974U Ref: ACS/105/009/2022/071

Dear Hafizul,

Thank you for your email.

Dear Xin Yu,

Kindly assist.

Best Regards,

**Elaine** | Reports

**LKK Auto Consultants Pte.Ltd.**

Phone: 6256-3561 Ext.111 email: [report@lkkauto.com](mailto:report@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933

---

**From:** Hafizul Farhan RAHMAT (SPF) <[Hafizul Farhan RAHMAT@spf.gov.sg](mailto:Hafizul_Farhan_RAHMAT@spf.gov.sg)>  
**Sent:** Friday, February 3, 2023 11:35 AM  
**To:** Elaine Kuan (LKK Auto) <[elainekuan@lkkauto.com](mailto:elainekuan@lkkauto.com)>  
**Cc:** Cui Fen ENG (SPF) <[ENG\\_Cui\\_Fen@spf.gov.sg](mailto:ENG_Cui_Fen@spf.gov.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: Survey Report & Invoice of Vehicle SND 5974U Ref: ACS/105/009/2022/071

Hi Elaine,

Can we check why the recommended repair cost for this case is outside the estimated upper range of repair cost?

<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,081.84</b>
------------------------------------	--	--	-----------------

Report Ref No. CS/SPF22011726/Twy3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,500**

*Best Regards,*

*Hafizul Farhan Bin Rahmat*

*Assistant Logistics Support Officer*

*Corporate Services Division / Police Logistics Department*



**Singapore Police Force** W [police.gov.sg](https://police.gov.sg) **FB** [fb.com/singaporepoliceforce](https://fb.com/singaporepoliceforce) **IG** [instagram.com/singaporepoliceforce](https://instagram.com/singaporepoliceforce)

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act 1935. Please notify the sender immediately if you receive this in error.

---

**From:** Elaine Kuan (LKK Auto) <[elainekuan@lkkauto.com](mailto:elainekuan@lkkauto.com)>

**Sent:** Wednesday, 1 February 2023 5:10 pm

**To:** Hafizul Farhan RAHMAT (SPF) <[Hafizul Farhan RAHMAT@spf.gov.sg](mailto:Hafizul_Farhan_RAHMAT@spf.gov.sg)>

**Cc:** Cui Fen ENG (SPF) <[ENG\\_Cui\\_Fen@spf.gov.sg](mailto:ENG_Cui_Fen@spf.gov.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** Survey Report & Invoice of Vehicle SND 5974U Ref: ACS/105/009/2022/071

Dear Hafizul,

Enclose Survey Report of SND 5974U.

Thank you.

Best Regards,

**Elaine** | Reports

**LKK Auto Consultants Pte.Ltd.**

Phone: 6256-3561 Ext.111 email: [report@lkkauto.com](mailto:report@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933