

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Together recent to the recent					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTOMOTIVE EN	GRG. & MGT. DIVISION (TP)	Re	ef:	CS/SPF22011726/y3	
	ACCIDENT CLAIM (SPORE POLICE I POLICE LOGISTIC 1 HEMMANT ROA	FORCE)		ate:	22/11/2022	
			Co	ode:	SPF	
1.						
	Insured Veh.	QX 548J	Veh. Inspected		SND 5974U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	ACS/105/009/2022/071	Excess (\$)		0.00	
	Assign From	HAFIZUL FARHAN	Assign Date		22/11/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5. General Information						
	Accident Date	16/11/2022	Inspection Date			
	Survey held at	TC AUTOCLINIC PTE LTD				
		25 LENG KEE RD SINGAPORE 159097				
5a.	5a. Remarks					

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.