

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 156/IC/TCAC/SAY/2022
DATE : 21-NOV-2022

SINGAPORE POLICE FORCE
POLICE LOGISTICS BASE (PLB)
1 HEMMANT ROAD
S(438675)
TEL : 64784840
FAX : 64784848
MR FARHAN

OWNER'S NAME : MR PHUA JUN HAO (PAN JUNHAO)
ADDRESS : BLK 643 YISHUN STREET 61
#08-280
S(760643)
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 5125186900
VEHICLE NO : SND5974U
MODEL CODE : FDWARV9P15HDA-C---
MODEL/YEAR : NISSAN KICKS 1.2L E-POWER PREMIUM MY2020
ENGINE NO : HR12442982C
CHASSIS NO : MNTFEAP15Z0005328
MILEAGE : 1 KM
DATE IN : 21/11/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH
ACCIDENT DATE : 16/11/2022

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SND5974U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	CONDUCT 3RD PARTY CLAIM SPF DATE:16/11/2022 TIME:2030HRS LOCATION:00PEN CARPARK YISHUN BLK642		
2	ZZ/002	REPAIR/REPLACE FRT BUMPER	390.00	
3	ZZ/003	RESPRAY FRT BUMPER	250.00	
		TOTAL LABOUR CHARGES	640.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SND5974U

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	BRKT FRT BUMPER FOG LAMP GARNISH	62252-5RY0A	124.60			
2	FRONT BUMPER	62022-5RY0H	552.30			
SUB TOTAL			676.90	0.00	0.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			135.38	0.00	0.00	
GRAND TOTAL			541.52	0.00	0.00	
OVERALL TOTAL			541.52			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SND5974U

TOTAL LABOUR CHARGES	640.00
TOTAL SPARE PARTS CHARGES	541.52

GRAND TOTAL	1181.52 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.