

VEHICLE NO. SLF 9006B

KIA KAREN

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT	
<u>PARTS (LIST ITEMS)</u>						
1	Front bumper	del/b, 1	627	1250.00		
1	Front bumper fog lamp RHS	CR	186	392.00		
1	Front bumper fog lamp cover RHS	NT		122.00	X	
2	Front bumper side retainer @98	o/s bent	38	196.00	12 C	
1	Front bumper lower cover	Torn		580.00		
1	RHS Headlamp	CR		982.00		
1	RHS Headlamp bracket	NS		154.00	X	
1	RHS Front fender	IP	384	782.00		
1	RHS Front fender inner shield	11		178.00	X	
1	RHS Front fender chrome moulding (top)	REFIX 11		0.00	X	
1	Front centre chrome grille	REFIX 11		0.00	X	
1	Front support panel	CR	482	492.00		
1	RHS Front lower arm	11		358.00	X	
1	RHS Front knuckle arm	11		328.00	X	
1	RHS Front knuckle arm bearing	11		250.00	X	
				6064.00		0.00
			less 10%	606.40	10%	0.00
				5457.60		0.00
<u>SPECIAL NETT ITEMS</u>						
1	RHS Front sports rim	11		980.00	X	
1set	Front bumper clips	CR		60.00	50	
1set	RHS Front fender inner shield clips	11		50.00	X	
1	Front number plate	REFIX 11		0.00	X	
1set	Front bumper PDC sensor	11		280.00	X	
1	RHS Front fender (DAILY DRIVEN) sticker	CR		100.00	60	
1	RHS Front fender yellow strip sticker	CR		60.00	40	
1	Front bumper yellow strip sticker	CR		90.00	60	
Total Parts				7077.60		0.00

L/br MS, AD Tony

Not Authored
 CR
 23/11/22
 L/s \$3500/
 4 days.

VEHICLE NO SLF 9006B KIA KAREN

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas; replace the damaged parts and components.	800.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	800.00	600
3	To conduct computerised wheel alignment test	120.00	✓
4	To remove and replace front RHS undercarriage parts (suspension system)	250.00	✓
5	To remove and re-fix wiring and check all electrical components at damaged areas & focus headlamp beam	150.00	20
6	To provide anti-rust treatment on affected areas	90.00	30
	Labour Total :	2210.00	
	TOTAL (PARTS & LABOUR):	9287.60	

PRELIMINARY ESTIMATE

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 3279
 103
 2951.10
 210
 1250
 4411.1
 3328