




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS3/SMR22011774/Gny3m4 Date: 03/02/2023 Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SMB 3614U	Veh. Inspected	E 93E
Policy No.		Coverage (\$)	0.00
Claim No.	BUS/11/22/5040	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	23/11/2022
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ CLS450	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	WDD2573592A012819	Colour	BLACK
Odometer	25764 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/35 R20	MICHELIN	6 mm
L/H Front Tyre	245/35 R20	MICHELIN	6 mm
R/H Rear Tyre	245/35 R20	MICHELIN	7 mm
L/H Rear Tyre	245/35 R20	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information			
Accident Date	21/11/2022	Inspect Date / Time	28/11/2022 (11:55 AM)
Survey held at	YAP MOTOR SERVICE PTE LTD BLK 7 SIN MING IND EST SEC C #01-80 & 82 SINGAPORE 575642		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$12,000-\$15,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	

Report Ref No. CS3/SMR22011774/Gny3m4

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.