

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: SOMPO	DATE	: 22/11/2022
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SMF6330Y		
MODEL	: HYUNDAI ELANTRA AD 1.6 GLS AT (AMS)		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 21-Nov-22
		TIME	: 18:15HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Distorted</i>	1	\$ 650.20	\$ 650.20
2	FRONT BUMPER SIDE RETAINER <i>new</i>	2	\$ 62.40	\$ 124.80
3	FRONT BUMPER UPPER INNER GARNISH <i>new</i>	1	\$ 60.00	\$ 60.00
4	FRONT BUMPER INNER GARNISH <i>new</i>	1	\$ 55.00	\$ 55.00
5	FRONT BUMPER FOGLAMP COVER <i>new</i>	1	\$ 110.50	\$ 110.50
6	HEADLAMP <i>lt.</i>	1	\$ 1,080.50	\$ 1,080.50
7	HEADLAMP LOWER BRACKET <i>new</i>	1	\$ 90.50	\$ 90.50
8	FRONT FENDER <i>Distorted</i>	1	\$ 530.50	\$ 530.50
9	FRONT FENDER INNER COWLING <i>Deformed</i>	1	\$ 130.50	\$ 130.50
10	FRONT KNUCKLE ARM <i>new</i>	1	\$ 366.90	\$ 366.90
11	FRONT KNUCKLE BEARING <i>new</i>	1	\$ 180.00	\$ 180.00
12	FRONT LOWER ARM <i>Best</i>	1	\$ 302.00	\$ 302.00
13	FRONT SHOCK ABSORBER <i>new</i>	1	\$ 450.50	\$ 450.50

3022.90
2418.32

TOTAL PRICE	\$ 4,131.90
LESS 20%	\$ 826.38
SUB TOTAL PRICE	\$ 3,305.52

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-----	-------------	-----	-------------	--------------

1	FRONT BUMPER CLIP(SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00
2	FRONT FENDER INNER COWLING CLIPS(SET) <i>Neu</i>	1	\$ 20.00	\$ 20.00
3	WHEEL RIM(SET) <i>ut</i>	1	\$ 1,200.00	\$ 1,200.00
4	WHEEL RIM TYRE <i>Neu</i>	1	\$ 380.00	\$ 380.00

490

TOTAL \$ 1,620.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	600	
3	WIRING CHECK	\$ 120.00	30	
4	REFOCUS HEADLAMP BEAM	\$ 80.00	X	
5	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 280.00	180	
6	FOUR WHEEL ALIGHMENT	\$ 100.00	80	

TOTAL \$ 2,980.00

1390

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,925.52
TOTAL LABOUR COST : \$ 2,980.00
TOTAL REPAIR COST : \$ 7,905.52

total: 4298.32

h/s: 3.412

06 Days

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :
NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: