11/22/22, 11:55 AM Estimate Report



Main Office: No. 22, Jalan Kilang, Singapore 159419 Tel: 6476 3333 Fax: 6271 5891

Service Centre: Block 1008, Bukit Merah Lane 3, #01-04/06/08/115, Singapore 159722 Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314 www.mova.com.sg GST Reg. No: M2-0088864-2

**Mova Spray Centre** 2K Oven Spray Painting System

12/11/2022

Power-M Automotive Pte Ltd Specialise In Car Air-con Services, Car Audio & Hi-Fi System.

Hilton Car Rental Centre **Hilton Auto Trading** Dealing In New/Used Cars, Hire Purchase & Insurance.

TP INSURER:

UNKNOWN

Allianz Insurance Singapore Pte. Ltd. (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type: THIRD PARTY Ref. No:

Policy No: Date of Loss:

Vehicle Reg. No.: SDV8133J Driveable?

Party At Fault: UNKNOWN

TOYOTA VELLFIRE, 2.5 Z G-EDITION 2WD Make/Model:

Vehicle Reg. Date: 20/06/2018 7SEAT (A)

Vehicle Colour: WHITE

Engine No: 2ARJ061925 AGH300183157 Chassis No:

Odometer: 0 KM

Paint Type:

Total Loss? NO Est. Duration of Repair (day) 3

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS		Amount
Parts		0.00
Miscellaneous Items		0.00
Labour		500.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	500.00
	+ GST 7.00% (S\$)	35.00
	Nett Amount (S\$)	535.00

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

## **REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Nov 2022)

Parts: M1-MPV TOYOTA VELLFIRE 2.5 Z G-EDITION 2WD 7SEAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SDV8133J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES

marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Estimates on Parts**

No.	Qty Part No.	Particulars	%Disc	%Depr	Amount	
1	1	*REAR DOOR LH -REPAIR	0.00	0.00	-	
		Sub Total (S\$)			0.00	
		+ Margin on L,N Items 10.00% (S\$)			0.00	
		Total Parts (S\$)			0.00	
Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS						

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

# **Estimates on Labour**

No	Particulars	Lab.Type	Amount
Lab	our Items		
1	TO REPAIR REAR DOOR LH, REMOVE & REFIX ATTACHMENT PARTS	New	200.00
2	TO SPRAY AFFECTED AREAS	New	300.00
		Gross Labour Cost (S\$)	500.00
	Report was unsubmitted during this print-out.  Generated using Marimen e-Claims IFAS		

< END OF ESTIMATES >