

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation
Non binding - Preview

Page 1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
GOH
BOON YONG
37 LORONG M TELOK KURAU
#02-02
Singapore 425316

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

22-11-2022
5211001170
200208384E
30001
2022034133/ 1
22-11-2022
Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMD7516H	5T13NZ	31-08-2018	WVGZZZ1TZJW111479	Touran 1.4 CL GT110 TSID7F	20

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
5TA853630A DPJ	Vw Sign Black/Bright Chro	1	pcs.	121.15	#1	121.15	129.63
5TA853687 ZZZ	Inscription Bright Chrome	1	pcs.	83.16	#1	83.16	88.98
5TA807417 GRU	NAME PLATE - TOURAN						
	Cover For Bumper Primed	1	pcs.	1,307.91	#1	1,307.91	1,399.46
	REAR BUMPER						
5QA061195	Load Edge Protection	1	pcs.	260.55	#1	260.55	278.79
5TA807568A 9B9	Spoiler Satin Black	1	pcs.	381.66	#1	381.66	408.38
5TA807305	Bumper	1	pcs.	706.15	#1	706.15	755.58
	REINFORCEMENT						
5TA807863	Attachment Strip	1	pcs.	75.42	#1	75.42	80.70
	BUMPER CTR BRACKET						
5TA807453	Guide Piece	1	pcs.	51.62	#1	51.62	55.23
5TA807454	LHR BUMPER BRACKET (UPPER)						
	Guide Piece	1	pcs.	51.62	#1	51.62	55.23
	RHR BUMPER BRACKET (UPPER)						
5TA807393	Guide Piece	1	pcs.	42.04	#1	42.04	44.98
	LHR BUMPER BRACKET (SIDE)						
5TA807394	Guide Piece	1	pcs.	42.04	#1	42.04	44.98
	RHR BUMPER BRACKET (SIDE)						
5TA945104	Reflector	1	pcs.	77.69	#1	77.69	83.13
	RHS REFLECTOR (OUTER)						
5TA945106	Reflector	1	pcs.	77.69	#1	77.69	83.13
	RHS REFLECTOR (INNER)						
5TA810972A	Wheelhouse Protector	1	pcs.	235.33	#1	235.33	251.80
	RHR FENDER LINER						
WHT005263	Rivet	4	pcs.	1.32	#1	5.28	5.65
	LABOUR	3	4	pcs.	#1	3,360.00	3,595.20
	SPRAY PAINT	3	4	pcs.	#1	3,200.00	3,424.00
	REVERSE SENSOR	1	pcs.	400.00	#1	400.00	428.00
	CHINA TAIPING DIRECT						
	DOA:19/11/2022						
	TP VEH NO:SKM1714T						
	SURVEY BY:						

Quotation valid till 29-11-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	10,479.31	7%	786.75	11,239.31	12,026.06

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Mr
GOH
BOON YONG
37 LORONG M TELOK KURAU
#02-02
Singapore 425316

Document no.
Document date 22-11-2022
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2022034133/ 1
Job order date 22-11-2022
Service Advisor Dass Anthonidas
Christopher

License plate	Model code	First registration	VIN	Model	Mileage
SMD7516H	5T13NZ	31-08-2018	WVGZZZ1TZW111479	Touran 1.4 CL GT110 TSID7F	20

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

Tanfulin 97495749/62563561
'WP' 24/11/22 @ 2:15pm
Resurvey before paint
tanfulin @ lkkauto.com
6-7 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary or Omitted List



VEHICLE NUMBER: SMD7516H

MODEL Touran 1.4

CLAIMS DETAILS

LABOUR DESCRIPTION		AMOUNT		
Total				\$0.00

No.	Item No.	Description	Qty	Unit Price	Discount	Amount
1	5TA821714D	RHR FENDER FOIL	1	\$ 37.22	nil ✓	\$ 37.22
			TOTAL:			\$37.22

Total Labour & Parts

\$37.22

SURVEY By