



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR22011827/Tvy3e2	
			Date: 09/03/2023	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 21J	Veh. Inspected	FBT 8920M
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/11/22/2010	Excess (\$)	0.00
	Assign From	ASHLENE LEE	Assign Date	24/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA NMAX	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	MH3SG5680NK134452	Colour	SILVER
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/70 R13	MAXXIS	5 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/70 R13	MAXXIS	5 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/11/2022	Inspection Date	24/11/2022
	Survey held at	HUA CHIN (2000) TRADING MOTOR SVC CENTRE 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	