

SIN BOON MOTOR CO

10 ADMIRALTY STREET,
#01-10/11, NORTHLINK BUILDING,
SINGAPORE 757695
TEL: 6257 8404, FAX: 6755 6214

DATE: 24/11/2022

FBS8698K - YAMAHA N-MAX 155 - YR2021 - ABS VEHICLE REPAIR QUOTATION

1	1 PC FRONT MUDGUARD	\$49.00
2	1 PC FENDER INNER	\$52.00
3	1 PC FENDER REAR	\$52.00
4	1 PC HANDLEBAR	\$58.00
5	1 PC HANDLE BRACKET	\$55.00
6	1 PC HANDLEBAR COVER	\$42.00
7	1 PC LAMP STAY	\$95.00
8	1 FORK UNDER BRACKET SET (FORK TUBE & FORK SPRING)	\$380.00
9	1 PC EXHAUST COVER	\$36.00
10	1 PC HEADLIGHT COMPLETE	\$240.00
11	1 PC COVER FRONT	\$48.00
12	1 PC FRONT LEFT SIGNAL COMPLETE	\$42.00
13	1 PC COVER FRONT 2 BUTTON	\$40.00
14	1 PC L/S BODY COWLING	\$75.00
15	1 PC R/S BODY COWLING	\$75.00
16	1 PC L/S PANEL 1	\$45.00
17	1 PC LEG SHIELD ASSY	\$55.00
18	1 PC CENTER COVER (OIL TANK)	\$55.00
19	1 PC L/S COVER 3 CENTER	\$60.00
20	1 PC L/S COVER 1 REAR	\$65.00
21	1 PC UNDER SKID PLATE	\$65.00
22	1 PC L/S MOLE SIDE COVER	\$40.00
23	1 PC R/S MOLE SIDE COVER	\$40.00
24	1 PC L/S FOOTREST BOARD	\$55.00
25	1 PC R/S FOOTREST BOARD	\$55.00
26	1 PC ARI BOX COVER	\$60.00
27	1 PC FRONT BRAKE DISC	\$75.00
28	1 PC FRONT WHEEL SHAFT	\$40.00
		<hr/>
		\$2,049.00
		LESS 10% \$204.90
		<hr/>
		\$1,844.10
29	TOW-TYPE COMPOUND	(NETT) \$60.00
30	REFORM CHASSIC	(NETT) \$400.00
31	LABOUR CHARGE FOR PART REPLACEMENT	(NETT) \$400.00
32	CARGO BOX	(NETT) \$210.00
		<hr/>
		\$2,914.10
		GST 7% \$203.99
		<hr/>
		\$3,118.09