



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22011867/Gvy3m4 Date: 14/03/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHD 6169S	Veh. Inspected	FBS 8698K	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/08/22/2002	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	25/11/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA NMAX 155 ABS CVT	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	MH3SG5680MK076986	Colour	SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	110/70-13	IRC	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/70-13	IRC	5 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	03/08/2022	Inspection Date	25/11/2022	
Survey held at	SIN BOON MOTOR CO 10, ADMIRALTY STREET #01-10/11 NORTHLINK BUILDING . SINGAPORE 757695			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	