

Shiau Chan (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Monday, 5 December 2022 4:28 PM
To: Shiau Chan (LKKAuto)
Subject: Re: CTI-PRS SLL 2577J SURVEYED BY IRFAN (OUR REF: CS3/CTI22011868/Sqp3)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SLL2577J, FOUND COR RANGE SHOULD BE 5-6K & REPAIR DAYS SHOULD BE 7 DAYS.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Monday, 5 December 2022 4:13 pm
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: CTI-PRS SLL 2577J SURVEYED BY IRFAN (OUR REF: CS3/CTI22011868/Sqp3)

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)