

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	EQ INSURANCE O	COMPANY LTD		Ref:	CS3/EQI22011899/Gqy3	
	5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI			Date:	28/11/2022	
				Code:	EQI	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XE 2575J	Veh. Inspected		SMJ 2145X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	DM22HO02045	Excess (\$)		0.00	
	Assign From	NEO JIE SI	Assign Date		28/11/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	4. Description of Damages					
5.						
	Accident Date	24/11/2022	Inspection Date	е	28/11/2022	
	Survey held at	WAH YU AUTOMOTIVE BODY WORK 176 SIN MING DRIVE #05-09 SINGAPORE 575721				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					