



凱摩多服務

KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。

Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 25/11/2022

Attn: The Motor Claims Department

Your Insured Vehicle - SKT 3790 Y

MSIG Insurance (S) Pte Ltd

4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

Tel : 6827 7888

Fax : 6827 7809

Dear Sir / Madam

Accident involving Vehicle Honda Civic SMQ 8684 E & SKT 3790 Y on 23/11/2022 at 13:10pm

1pc	Front Fender LH <i>Dented</i>	450.80	✓
1pc	Front Head Lamp LH <i>lit</i>	675.90	✓
1pc	Front Head Lamp Moulding LH <i>new</i>	112.20	+
1pc	Front Fender Lamp LH <i>new</i>	74.30	+
1pc	Front Grille <i>cracked</i>	214.50	✓
1pc	Front Haed Lamp Lower Garnish LH <i>new</i>	30.80	X
1pc	Front Bumper <i>Distorted</i>	579.90	✓
1pc	Front Bumper Side Retainer LH <i>new</i>	19.80	+
12pcs	Front Bumper Clips <i>new</i> \$3.90 x 12pcs	46.80	30
1pc	Front Bumper Ford Lamp LH <i>new</i>	288.90	+
1pc	Front Bumper Ford Lamp Garnish LH <i>lit</i>	102.80	✓

Less *10%* - **259.67**

2,596.70

2,337.03

1pc Front Number Plate

65.00 x nn

To dismanlte & replace damage parts,panel beat where necessary

To putty,apply primer & spray paint on the affecte portion.

Computer Wheel Alignment

To check wiring functions.

680.00

750.00

120.00

100.00

4,052.03

28/11/22

1/5 04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: *Xia Yu.*
Date: