

Claim Summary	
Ref No ynYv6aQ7mh	III Claim No.
Workshop AutoSprint Pte Ltd	Insurer India International Insurance Pte Ltd (Warranty Claims)
Created At 17/11/2022	Status Insurer Review

Claim Details		
Date of Notification		Date of Loss
16/11/2022		16/11/2022
Details of Loss		
48V Battery Malfunction - Replace		
Claim Item	Price	Recommended Price
1. 48V Battery	\$2915.00	\$0.00
Claim Labour		
1. Labour	\$60.00	\$0.00
2. Re-Programming & Coding for New 48V battery	\$935.00	\$0.00
Total Claims Amount	\$3910.00	\$0.00
Additional Remarks	Surveyor Reports	

Vehicle & Policy Information	
Car Plate SMY7674Z	Chassis Number W1N2539842V250746
Make & Model Mercedes GLC300	Mileage 19846
Owner NRIC/UEN Number 200312900K	Policy Certificate Number C04287
Policy Coverage Period 25/03/2021 to 24/03/2026	Insured Name Gao DeChun
Insured NRIC/UEN Number 422F	

Initial Claim Attachments

Details of Loss Attachment

- [SMY7674Z LOC.pdf](#)
- [WhatsApp Image 2022-11-17 at 11.49.01 AM.jpeg](#)
- [WhatsApp Image 2022-11-17 at 11.49.02 AM \(1\).jpeg](#)
- [WhatsApp Image 2022-11-17 at 11.49.02 AM \(2\).jpeg](#)
- [WhatsApp Image 2022-11-17 at 11.49.02 AM.jpeg](#)
- [SMY7674Z Mileage.jpeg](#)
- [SMY7674Z Chassis Nos.jpeg](#)
- [SMY7674Z Fault Code.jpeg](#)
- [SMY7674Z Dia Rep.pdf](#)

Quotation Attachment

- [SMY7674Z Quotation.pdf](#)

Service Record Attachment

- [SMY7674Z Svc Inv.pdf](#)
- [SMY7674Z Svc Inv 1.pdf](#)
- [SMY7674Z Svc Inv 2.pdf](#)
- [SMY7674Z Svc Inv 3.pdf](#)