

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 09 Jan 2023

**Preliminary Advice**

|                    |                                                                                                            |                         |              |
|--------------------|------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : GBD2691Y                                                                                                 | Accident Date           | : 22/11/2022 |
| TP Vehicle No      | : SKS3907J                                                                                                 | Assignment Date         | : 25/11/2022 |
| Make               | : TOYOTA CAMRY                                                                                             | Est. Duration of Repair | : 3          |
| Date of Inspection | : 29/11/2022                                                                                               |                         |              |
| Inspection At      | : AH LIM MOTOR COMPANY (AMK)<br>10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT<br>SINGAPORE 568047 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 5,879.00 |
| Revised Amount              | :S\$ | 2,334.89 |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 2,334.89 |

|                 |      |          |
|-----------------|------|----------|
| Lump Sum Repair | :S\$ | 1,850.00 |
|-----------------|------|----------|

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.