

## Shiau Chan (LKKAuto)

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Tuesday, 6 December 2022 1:26 PM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** Re: ASM-TP FBB 1616H SURVEYED BY TAUFIKH (OUR REF: CS/ASM22011930/Tqp3)

Dear Shiau Chan,

Audit check done for FBB1616H, found not economical to repair.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)>  
**Sent:** Tuesday, 6 December 2022 12:04 pm  
**To:** Simon Ho (LKKAuto) <[SimonHo@lkkauto.com](mailto:SimonHo@lkkauto.com)>  
**Subject:** ASM-TP FBB 1616H SURVEYED BY TAUFIKH (OUR REF: CS/ASM22011930/Tqp3)

Dear Simon,

For your audit.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)