



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL C/O MCLARENS SINGAPORE PTE LTD 61 ROBINSON ROAD, #09-01, 61 ROBINSON, SINGAPORE 068893			Ref: CS/MCS22011938/Avy3e2 Date: 31/01/2023 Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	DRIVING BOC	Veh. Inspected	SMK 4078M	
Policy No.	C22-10/35/PL-III	Coverage (\$)	0.00	
Claim No.	LPL2022D0010534	Excess (\$)	0.00	
Assign From	ERNEST KHONG	Assign Date	28/11/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA JAZZ	c.c	1318	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JHMGK3850KS212980	Colour	BROWN	
Odometer	60885 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	175/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	175/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	175/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/11/2022	Inspection Date	29/11/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	