



**JACK**  
DRIVE WITH**CARS**  
ASSURANCE

## ESTIMATE

|                               |
|-------------------------------|
| DATE OF ACCIDENT : 25/11/2022 |
| VEHICLE : SLD4079J            |
| MAKE & MODEL : MERC C180      |
| INSURANCE : LIBERTY           |
| SURVEYOR : LKK TAUFIK         |

| PARTS |                                       | AMOUNT               |
|-------|---------------------------------------|----------------------|
| 1.    | REAR BUMPER                           | \$ 1200 <i>de</i>    |
| 2.    | REAR BUMPER LOWER LIPS                | \$ 450 <i>de</i>     |
| 3.    | REAR BOOT                             | \$ 2300 <i>bt</i>    |
| 4.    | REAR BOOT INNER COVER                 | \$ 380 <i>X</i>      |
| 5.    | REAR BOOT WEATHERSTRIP                | \$ 220 <i>twi</i>    |
| 6.    | REAR BOOT CHROME GARNISH              | \$ 180 <i>aut</i>    |
| 7.    | REAR BOOT SIDE GARNISH - LEFT & RIGHT | \$ 200 <i>aut</i>    |
| 8.    | REAR END PANEL                        | \$ 680, <i>bt?</i>   |
| 9.    | REAR END PANEL TOP COVER              | \$ 230 <i>de</i>     |
| 10.   | TAIL LAMP - LEFT                      | \$ 2550 <i>Cover</i> |
| 11.   | TAIL LAMP - RIGHT                     | \$ 2550 <i>Cover</i> |
| 12.   | REAR SUPPORT BEAM                     | \$ 980 <i>bt</i>     |
| 13.   | BOOT LOCK - UPPER                     | \$ 320 <i>?</i>      |



# JACK

DRIVE WITH

# CARS

ASSURANCE

|     |                                     |  |                    |
|-----|-------------------------------------|--|--------------------|
| 14. | BOOT LOCK - LOWER                   |  | \$ 180 x           |
| 15. | BOOT LOCK COVER - UPPER             |  | \$ 90 <i>mis</i>   |
| 16. | REAR UNDERCARRIAGE COVER            |  | \$ 330 x           |
| 17. | FRONT BUMPER                        |  | \$ 2500 <i>de</i>  |
| 18. | FRONT BUMPER BRACKET - LEFT & RIGHT |  | \$ 150 x           |
| 19. | FRONT BUMPER GARNISH                |  | \$ 380 x           |
| 20. | FRONT BUMPER CHROME GARNISH         |  | \$ 250 <i>at</i>   |
| 21. | FRONT BUMPER UPPER GRILLE           |  | \$ 560 <i>de</i>   |
| 22. | FRONT SUPPORT BEAM                  |  | \$ 680 <i>bb</i>   |
| 23. | FRONT SUPPORT BEAM UPPER PANEL      |  | \$ 430 <i>bt</i>   |
| 24. | FRONT SUPPORT PANEL                 |  | \$ 900 x           |
| 25. | FRONT SUPPORT PANEL CENTRE BRACKET  |  | \$ 310 <i>bt</i>   |
| 26. | BONNET                              |  | \$ 3100 <i>Ry</i>  |
| 27. | BONNET HINGE - LEFT & RIGHT         |  | \$ 300 x           |
| 28. | HEADLAMP - LEFT                     |  | \$ 2800 <i>cu</i>  |
| 29. | SEAT BELT - FRONT RIGHT             |  | \$ 1800 <i>ret</i> |
| 30. | SEAT BELT - FRONT LEFT              |  | \$ 1800 x          |
| 31. | SEAT BELT - REAR RIGHT              |  | \$ 1800 <i>at</i>  |
| 32. | SEAT BELT - REAR LEFT               |  | \$ 1800 <i>at</i>  |
|     | <i>Headlamp RH cu \$2800</i>        |  |                    |
|     | <b>SPECIAL NETT</b>                 |  |                    |





# JACK CARS

DRIVE WITH ASSURANCE

|     |                                                                                                                                 |             |                                  |
|-----|---------------------------------------------------------------------------------------------------------------------------------|-------------|----------------------------------|
| 1.  | FRONT NUMBER PLATE & COVER                                                                                                      |             | \$ 150 <sup>45</sup> <i>arg</i>  |
| 2.  | REAR NUMBER PLATE & COVER                                                                                                       |             | \$ 150 <sup>45</sup> <i>int</i>  |
| 3.  | REVERSE SENSOR                                                                                                                  |             | \$ 320 <sup>250</sup> <i>int</i> |
| 4.  | FRONT PARKING SENSOR                                                                                                            |             | \$ 300 <i>x</i>                  |
| 5.  | AIRBAG SENSOR                                                                                                                   |             | \$ 500 <i>x</i>                  |
| 6.  | IMPACT SENSOR                                                                                                                   |             | \$ 500 <i>x</i>                  |
| 7.  | AIRBAG CONTROL MODULE                                                                                                           |             | \$ 1500 <i>aut</i>               |
| 8.  | "MERC" EMBLEM – FRONT                                                                                                           |             | \$ 150 <i>int</i>                |
| 9.  | "MERC" EMBLEM COVER – FRONT                                                                                                     |             | \$ 230 <i>de</i>                 |
| 10. | "MERC" EMBLEM – REAR                                                                                                            |             | \$ 100 <i>int</i>                |
| 11. | TOW HOOK COVER                                                                                                                  |             | \$ 100 <i>mts</i>                |
| 12. | REAR END PANEL SEALANT                                                                                                          |             | \$ 200 <i>60x</i>                |
| 13. | CLIPS , SCREWS & RIVETS                                                                                                         |             | \$ 250 <i>50x</i>                |
|     |                                                                                                                                 |             |                                  |
|     | <b>LABOUR</b>                                                                                                                   |             |                                  |
| 1.  | TO PUTTY & SPRAY PAINT OF AFFECTED AREA                                                                                         | <i>1400</i> | \$ 2500                          |
| 2.  | TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS. |             | \$ 2500<br><i>1400</i>           |
| 3.  | TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE                                                                                       | <i>50</i>   | \$ 250                           |
| 4.  | TO REMOVE AND REINSTALL TAILGATE COMPONENTS                                                                                     | <i>60</i>   | \$ 200                           |
| 5.  | TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY                                                                                    | <i>60</i>   | \$ 250                           |
| 6.  | TO REMOVE & REINSTALL SENSORS                                                                                                   | <i>50</i>   | \$ 200                           |



# JACK CARS

DRIVE WITH ASSURANCE

|    |                                                               |              |
|----|---------------------------------------------------------------|--------------|
| 7. | PROGRAMMING (AIRBAG , HEADLIGHT , SEAT BELT & CONTROL MODULE) | \$ 700 200   |
| 8. | ANTI RUST TREATMENT                                           | \$ 200 50    |
|    |                                                               |              |
|    |                                                               |              |
|    | PARTS - 10%:                                                  | \$ 29,160    |
|    | SPECIAL NETT :                                                | \$ 4,450     |
|    | LABOUR :                                                      | \$ 6,800     |
|    | TOTAL :                                                       | \$ 40,410    |
|    | 7% GST :                                                      | \$ 2,828.70  |
|    | GRAND TOTAL :                                                 | \$ 43,238.70 |

Tanjun 97495749  
WP 29/11/22  
Tanjun @ khando.com  
To check L/S or P/P.  
Resurvey before paint / after paint -  
10 days

**Jack Auto Consultancy** hereby notify  
the Repairer of the following:  
• To resurvey before/spray painting  
• To display damaged parts during resurvey confirmation  
• Parts prices are subject to confirmation  
• Third party survey is "Without" confirmation  
• No illegal modification is allowed  
• Supplementary item/et has to be supplied  
is subject to final approval by Jack Auto Consultancy.

Acknowledged by Repairer  
Signature:  
Date: