




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: KHOR SAW THENG			Ref: CS3/ASM22011955/Gqp3e2 Date: 17/04/2023 Code: HSB	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 3266P	Veh. Inspected	SNG 237G
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M04FC2	Excess (\$)	0.00
	Assign From	KHOR SAW THENG	Assign Date	29/11/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA CAMRY HYBRID 2.5	c.c	2487
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JTNB23HK203063377	Colour	WHITE
	Odometer	37172 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	MICHELIN	7 mm
	L/H Front Tyre	215/55 R17	MICHELIN	7 mm
	R/H Rear Tyre	215/55 R17	MICHELIN	7 mm
	L/H Rear Tyre	215/55 R17	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information				
	Accident Date	19/11/2022	Inspect Date / Time	30/11/2022 (12:30 PM)
	Survey held at	A-TEC MOTORZ PTE LTD 39 WOODLAND CLOSE #02-43 MEGA @WOODLAND SINGAPORE 737856		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$400-\$600			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	

Report Ref No. CS3/ASM22011955/Gqp3e2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.