

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22011975/TPA3Q2**Date:** 10/03/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0000326_02

Claimant Vehicle No : SHB4487Y**Insured Vehicle No :** SLX3426S

Date of Loss: 25/11/2022

Nature of Claim: TP

Claim No: MFL2022D0010885

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHB4487Y**

Make & Model: HYUNDAI I40, 1.7 D CRDi (A)

Engine No: D4FDGU700055

Reg. Date: 29/12/2016 (Man. Year: 2016)

Chassis No: KMHLB41UMHU097719

Colour: Blue

Odometer: 560636 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,924.16	451.36	4,472.80	90.83
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	2,080.00	1,125.00	955.00	45.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,015.16	1,587.36	5,427.80	77.37
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	7,015.16	1,250.00	5,765.16	82.18
+ GST 7.00/7.00% (S\$)	491.06	87.50	403.56	82.18
Nett Amount (S\$)	7,506.22	1,337.50	6,168.72	82.18
+ Loss of Use (4.0 x S\$40.00/day) (S\$)		160.00		
+ Car Rental (4.0 x S\$114.95/day) (S\$)		459.80		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,964.75		
Global Sum Settlement (S\$)		1,950.00		

INSPECTION

Date of Assignment: 28/11/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 28/11/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)

Estimated Period of Repair: 2.0 days

59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2023)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB4487Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER LH	Repair	2,171.40 FL	*- FL
2	1		*ROCKER COVER GARNISH LH	Repair	732.80 FL	*- FL
3	1		*REAR DOOR LH	Repair	2,416.80 FL	*- FL
4	1		*WHEEL HUB CAP RR LH	Cracked	214.20 FL	*214.20 FL
5	1		*REAR DOOR COMFORTDELGRO & APPS STICKER LH	Necessary	80.00 F	*80.00 F
6	1		*RENEW ADVERTISEMENT STICKER	Cut	200.00 F	*200.00 F
7	1		*RR TYRE LEFT	Not Necessary	216.00 F	*- F
					Sub Total (S\$)	6,031.20 494.20
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,107.04 42.84
					Total Parts (S\$)	4,924.16 451.36

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	900.00	525.00
2	SPRAY PAINTING CHARGE	New	1,000.00	600.00
3	TRANSFER OF DOOR	New	120.00	0.00
4	TUFF KOTE	New	60.00	0.00
Gross Labour Cost (\$\$)			2,080.00	1,125.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >