



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|-----------------|---|--|
| LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428 | | | Ref: CS/LIP22011979/Kvy3m4 Date: 21/12/2022 Code: LIP | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SGB 108E | Veh. Inspected | SKU 5620L | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | AVS22/3328 | Excess (\$) | 0.00 | |
| Assign From | ANDY SEAH | Assign Date | 29/11/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | TOYOTA ALTIS (A) | c.c | 1598 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | MR053REH104535735 | Colour | METALLIC SILVER | |
| Odometer | 202488 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 205/55 R16 | YOKOHAMA | 9 mm | |
| L/H Front Tyre | 205/55 R16 | YOKOHAMA | 9 mm | |
| R/H Rear Tyre | 205/55 R16 | YOKOHAMA | 9 mm | |
| L/H Rear Tyre | 205/55 R16 | YOKOHAMA | 9 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 26/11/2022 | Inspection Date | 29/11/2022 | |
| Survey held at | LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645. | | | |
| 5a. Remarks | | | | |
| A)REGISTRATION DATE: 31 JULY 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 5 Working Days | |