



Your Ref : CMTD2202492/AGC

Date: 15th December 2022

Our Ref : CS/SMO22011987/Awy3m4

M/s Sompo Insurance Singapore PL

50 Raffles Place #03-03

Singapore Land Tower

Singapore 048623

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FBK 714S
INSURED VEHICLE: CB 7433S
ACCIDENT ON 15/07/2022**

Instruction was received to inspect the vehicle Reg. No. FBK 714S. The inspection was conducted on 30/11/2022 at the premises of M/s HP Moto, 8 Kaki Bukit Avenue 4 #04-32 Premier@Kaki Bukit, Singapore 415875.

The following vehicle information was recorded:


Registration Number	: FBK 714S
Make/Model	: Honda ADV750
Year of Registration	: 2019
Body Colour	: Red
Chassis Number	: JH2RC95A5KK203758
Engine Capacity	: 745 cc

The vehicle sustained damages at the rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 24,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 2,226.00)
Nett Liability	<u>S\$ 21,774.00</u> =====

Vehicle Inspected By:



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser



K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),

MASME(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIIIE(mech), MinstAEA, MFIEA,

MIRTE,MIMI,MSAE,MCIARD, AM,NIJAAR(USA),

AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.