

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01054/2022/EQ
DATE : 23-Nov-22
WIP : 51899

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/11/2022

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS KWOK TIAN CHEE
ADDRESS : BLK 6 LORONG LEW LIAN
#03-120
SINGAPORE 531006
TELEPHONE : HP +65 98529823
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800088216-03
VEHICLE NO : **SJJ 3920 D**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 26/7/2018
ENGINE NO : CHZ 466306
CHASSIS NO : WAUZZZ8V9J1069554
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Nov-22
PLACE OF ACCIDENT : YISHUN AVE 2 (IN FRONT OF KHATIB STATION)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJJ 3920 D

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	X-
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00 1000	✓
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00 1100	✓
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	✓ ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$ 5,282.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJJ 3920 D

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>Delint</i>	1	\$ 2,432.00	✓	1945.60
2	FRONT BUMPER GUIDE SECTION - LH <i>Re new</i>	1	\$ 43.00	7 X	
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Re new</i>	1	\$ 571.00	X	
4	FRONT BUMPER CLOSING ELEMENT - LH <i>Re new</i>	1	\$ 318.00	+	
5	FRONT BUMPER TRIM COVER - LH	1	\$ 182.00	+	
6	FRONT WHEEL HOUSING LINER ADAPTER - LH <i>Re new</i>	1	\$ 42.00	+	
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Not rec</i>	1	\$ 210.00	+	
8	FRONT FENDER - LH <i>Deinted</i>	1	\$ 954.00	✓	763.00
9	FRONT FENDER RIVET <i>Re new</i>	5	\$ 19.00	7	15.00
10	FRONT FENDER ATTACHMENT PARTS <i>Re new</i>	1	\$ 75.00	X	
11	FRONT FENDER BRACKET - LH CENTER <i>Re new</i>	1	\$ 46.00	7 X	
12	FRONT FENDER BRACE <i>Bent</i>	1	\$ 107.00	7	85.60
13	FRONT FENDER BRACKET - LH <i>Re new</i>	1	\$ 31.00	7 X	
14	FRONT WHEEL HOUSING LINER - LH <i>Re new</i>	1	\$ 183.00	7 X	
15	FRONT ALUMINIUM RIM <i>cut</i>	1	\$ 1,303.00	✓	1042.40
16	FRONT ALUMINIUM RIM RUBBER VALVE <i>Re new</i>	1	\$ 4.00	7	2.96
17	HEADLIGHT - LH <i>2</i>	1	\$ 5,879.00	+	
18	LIFT CYLINDER - LH <i>Re new</i>	1	\$ 156.00	+	
19	LIFT CYLINDER HOSE	1	\$ 78.00	+	
20	SUNDRIES <i>Re new</i>		\$ 500.00	7	592
TOTAL SPARE PARTS			\$ 13,133.00		
TOTAL LABOUR CHARGES			\$ 5,282.00		
GRAND TOTAL			\$ 18,415.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *30/11/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Veron.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJJ 3920 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Delint</i>	1	\$ 2,432.00	✓
2	FRONT BUMPER GUIDE SECTION - LH ?	1	\$ 43.00	?
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>me</i>	1	\$ 571.00	+
4	FRONT BUMPER CLOSING ELEMENT - LH <i>free</i>	1	\$ 318.00	+
5	FRONT BUMPER TRIM COVER - LH	1	\$ 182.00	+
6	FRONT WHEEL HOUSING LINER ADAPTER - LH <i>me</i>	1	\$ 42.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>not nec.</i>	1	\$ 210.00	+
8	FRONT FENDER - LH <i>Revised</i>	1	\$ 954.00	✓
9	FRONT FENDER RIVET ?	5	\$ 19.00	?
10	FRONT FENDER ATTACHMENT PARTS <i>me</i>	1	\$ 75.00	+
11	FRONT FENDER BRACKET - LH CENTER ?	1	\$ 46.00	?
12	FRONT FENDER BRACE <i>But.</i>	1	\$ 107.00	✓ <i>HL/S</i>
13	FRONT FENDER BRACKET - LH ?	1	\$ 31.00	?
14	FRONT WHEEL HOUSING LINER - LH ?	1	\$ 183.00	?
15	FRONT ALUMINIUM RIM <i>cut</i>	1	\$ 1,303.00	✓
16	FRONT ALUMINIUM RIM RUBBER VALVE ?	1	\$ 4.00	?
17	HEADLIGHT - LH <i>2</i>	1	\$ 5,879.00	+
18	LIFT CYLINDER - LH <i>not in</i>	1	\$ 156.00	+
19	LIFT CYLINDER HOSE	1	\$ 78.00	+
20	SUNDRIES ?		\$ 500.00	?
TOTAL SPARE PARTS			\$ 13,133.00	
TOTAL LABOUR CHARGES			\$ 5,282.00	
GRAND TOTAL			\$ 18,415.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Adrian Ling
Resurveyed.
HL/S