

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	29 Nov 2022 19:38	Clm Veh Model Changed		[] Merimen Administrator
2	29 Nov 2022 19:38	Clm Created	Reg No: SLS8512U. Policy No: 1700063086-05. Acct Date: 2022/11/29. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SA S:SP1422BT0003	[I] Merimen Administrator
3	01 Dec 2022 10:53	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	01 Dec 2022 10:53	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	01 Dec 2022 10:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	01 Dec 2022 10:53	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/12/12	[A] CELINE FONG
7	01 Dec 2022 10:53	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	01 Dec 2022 10:53	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	01 Dec 2022 10:53	Clm Veh Model Changed	(205236) AUDI Q2 999cc 1.0 TFSI S TRONIC (A).	[A] CELINE FONG
10	01 Dec 2022 10:53	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
11	01 Dec 2022 11:50	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	01 Dec 2022 11:50	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	01 Dec 2022 11:50	Clm Dtl Modified	JPJ Reg. Date: -> 2017/10/09.	[A] Elaine Kuan Hwa Meen
14	01 Dec 2022 11:50	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	01 Dec 2022 12:09	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/12/12	[A] HUEY YON
16	01 Dec 2022 12:10	Adj Mandate Request	Cur.Req:6235.00:damages consistent.repair cost economical. We have not authorise repair.	[A] HUEY YON
17	01 Dec 2022 16:07	Clm Registration Modified	Init.Est.->5,000 - 6,000. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Azlan, Syazairdina
18	01 Dec 2022 16:49	Clm Registration Modified	Excess: -> 800.00.	[I] Azlan, Syazairdina
19	02 Dec 2022 17:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/12/12. Mandate Remarks: Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair	[I] Lim, Kok-Chong
20	02 Dec 2022 17:15	Adj Mandate Set	Approved:5701.00:Vehicle may commence repair Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From  Date To  Audit Type

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2877665	01 Dec 2022 11:50:53	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLS8512U		11.00

