

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melody Teoh

Date: 05 Dec 2022

Preliminary Advice

Vehicle No	: XE6697P	Accident Date	: 26/11/2022
Make	: SCANIA P410A4X2NZ	Policy No.	: DMCG22009586
Assignment Date	: 01/12/2022	Excess	: S\$2,500.00
Date of Inspection	: 01/12/2022	Est. Duration of Repair	: 10
Inspection At	: WOON MENG MOTOR PTE LTD (BUKIT BATOK) 50 BUKIT BATOK STREET 23,, #01-06 MIDVIEW BUILDING SINGAPORE 659578		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,189.76
Revised Amount	:S\$	22,110.36
Check Items (Estimated)	:S\$	4,459.40
Total	:S\$	26,569.76

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	180,000.00
COE / PARF Rebate	:S\$	32,335.00
Salvage Value	:S\$	
Margin for Repair	:S\$	147,665.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :