

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547519
FAX :

Date : 30/11/2022
To : ECICS LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 18/10/2022

Vehicle No : SMD-2989-J

Make & Model : MITSUBISHI OUTLANDER 2.0 (A) ELEGANCE

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	REAR BUMPER <i>de /</i>	867.00	
1	REAR BUMPER RETAINER LH <i>X</i>	49.00	
1	REAR BUMPER BRACKET LH <i>X</i>	92.00	
10	REAR BUMPER CLIPS <i>an /</i>	50.00	
1	TAILGATE <i>repair</i>	RESTORE	
1	EMBLEM - OUTLANDER <i>an /</i>	89.00	
1	TAILGATE LAMP LH <i>an /</i>	439.00	
1	TAILGATE CHROME GARNISH <i>repair</i>	497.00	
1	TAILLAMP LH <i>X</i>	593.00	

Date : 30/11/2022
To : ECICS LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 18/10/2022

Vehicle No : SMD-2989-J Make & Model : MITSUBISHI OUTLANDER 2.0 (A) ELEGANCE

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	
	Sub Total	1630.00	

LKK Auto Consultants hereby notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4,258.40

Remarks:

SUB TOTAL

GST 7.0 % 298.09

TOTAL 4,556.49

Surveyor's name: Rasul - Hp 90010068

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 01/12/22 @ 15W

3 days / 45 P/P
Resurvey after repair
before paint

Date : 30/11/2022

To : **ECICS LIMITED**

ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 18/10/2022

Vehicle No : SMD-2989-J

Make & Model : MITSUBISHI OUTLANDER 2.0 (A) ELEGANCE

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR FENDER LH	RESTORE	
1	END PANEL	RESTORE	
	Sub Total	2676.00	
	Discount 10% On Parts	(267.60)	
	<u>Special Nett Item</u>		
1	REVERSE SENSOR	220.00	
	Sub Total	220.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	800.00	400
	TO RESPRAY AFFECTED AREAS	800.00	400

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 943G

Vehicle Details

Vehicle No.: SMD2989J

Vehicle to be Exported: No

Intended Deregistration Date: 04 Dec 2022

Vehicle Make: MITSUBISHI

Vehicle Model: OUTLANDER 2.0 CVT

Primary Colour: Black

Manufacturing Year: 2018

Engine No.: 4J11YP9397

Chassis No.: GF7W0402079

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$19,433.00

Original Registration Date: 13 Aug 2018

First Registration Date: 13 Aug 2018

Transfer Count: 1

Actual ARF Paid: \$19,433.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 12 Aug 2028

PARF Rebate Amount: \$14,574.00

Intended COE Rebate Details

COE Expiry Date: 12 Aug 2028

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$37,989.00

COE Rebate Amount: \$21,608.00

Total Rebate Amount: \$36,182.00

Mitsubishi Outlander 2.0A

[Overview](#)
[Financial](#)
[Accessories](#)
[Similar](#)
[Research](#)
[Photos](#)
[Map](#)


Singapore
Vehicle
Traders
Association


Price
\$98,800
Depreciation
\$15,490 /yr
[View models with similar depre](#)
Reg Date
31-Aug-2018
(5yrs 8mths 26days COE left)
Mileage
106,314 km (24.9k /yr)
Manufactured
2018
Road Tax
\$1,210 /yr
Transmission
Auto
Dereg Value
\$32,558 as of today (change)
OMV
\$19,675
COE
\$31,000
ARF
\$19,675
Engine Cap
1,998 cc
Power
110.0 kW (147 bhp)
Curb Weight
1,480 kg
No. of Owners
2
Type of Vehicle
SUV