

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKB37D (Insd veh)	Model:	TOYOTA HARRIER 2.0 G
	SLW1718T (TP veh)		GRADE (A)
Date of Accident:	30/11/2022		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		20,549.10
Final Repair Cost	:	\$		9,951.00
Loss of Use	:	\$		800.00
				8.00 days at \$100.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		10,753.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown				
1)	Tan Lim Motor Pte Ltd	:	\$	10,753.00
2)		:	\$	
3)		:	\$	

JOANNE LEE KHANG MIN

18 Feb
2023

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))