



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22012042/Kwy3m4 Date: 05/06/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 7363B	Veh. Inspected	SKN 1213S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D22003788MFBP	Excess (\$)	0.00	
Assign From	HARMINDER KAUR	Assign Date	01/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES S350 (A)	c.c	2987	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD2221322A086453	Colour	METALLIC DARK BLUE	
Odometer	534446 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50R18	GOODYEAR	8 mm	
L/H Front Tyre	245/50R18	GOODYEAR	8 mm	
R/H Rear Tyre	245/50R18	GOODYEAR	8 mm	
L/H Rear Tyre	245/50R18	GOODYEAR	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/11/2022	Inspection Date	01/12/2022	
Survey held at	160 SIN MING DRIVE AUTOCITY #02-04 (S) 575722			
Repairer	CAR TIMES AUTOLUTION PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	