

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 202222008335/SL Date: 16th Mar 2023

Our Ref: CS6/AIS22012051/Tvy3e2

M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

DESKTOP SURVEY OF ACCIDENT VEHICLE SKT 8618E ACCIDENT ON 21/11/2022

We thank you for your instruction on 01/12/2022.

The following vehicle information was recorded:

Registration Number : SKT 8618E

Make & Model : Mercedes Benz CLA180 (R18 BI)

Chassis Number : WDD1173422N216610

Year of Registration : 2015 Engine Capacity : 1595 cc

- 1. The vehicle sustained damages at the front portion. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.