

ASS. REC BY: T. J. M.

REF: CC3/ ALG. 22012073/Tvp3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 (OD) TP / MS/TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop/s _____
 of _____
 Insured: _____
 Policy No. 1700072065-05
 Claims No. 4876089887SG
 Sum Insured: _____ Excess: 600
 (Client's Record)
 Make of Velt _____

Veh No: SLT 790 Yr Regn: 20/7, Nov
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mercedes C.C. 1984
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 44515 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: W144 227 F57 J1A038 760
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 245/40R18
 R: 7 -
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (P/R) / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 8 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 21/11/2022 D.O.I. 01/12/22
 Survey held at Premium 46i
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$128k
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
9/3/23	Final fig \$15,489.52 confirmed by email (Red 9360.48, 37%)

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) _____
 Date/Time, File Return to?

Days Of Repair: 8
 Resurvey No. of Trip: 1

2) 27/3/23-typist
 Report Format: Merimen
 Lump Sum / L.B.K. (\$): \$15,489.52

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. rvs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. \$ _____
 Photos _____
 Others _____
 TOTAL _____



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/01051/2022/EQ
DATE : 23-Nov-22
WIP : 51823

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/11/2022

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

OWNER'S NAME : DR SOH CHEE CHEONG REUBEN (SU ZHIZHONG, REUBEN)
ADDRESS : 7A HOLLAND HILL
#04-08
SINGAPORE 278732
TELEPHONE : HP +65 96473700
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700072065-05
VEHICLE NO : **SLT 790 E**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 1/11/2017
ENGINE NO : CVK 047766
CHASSIS NO : WAUZZZF57JA038760
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Nov-22
PLACE OF ACCIDENT : ORANGE GROVE ROAD



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 790 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. S/N \$	900.00 ✓	
2	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. S/N \$	460.00 ✓	
3	TO DISMANTLE AND RENEW RHS FRONT DOOR, RHS REAR DOOR AND RHS SILL PANEL TRIM. TO REPAIR RHS REAR FENDER. TO REMOVE AND REINSTALL REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. \$	4,500.00	2500
4	TO REPRAY RHS FRONT DOOR, DOOR HANDLE, RHS REAR DOOR, RHS SILL PANEL TRIM, RHS REAR FENDER AND REAR BUMPER. \$	5,500.00	2750
5	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT. S/N \$	380.00 ✓	
6	TO CARRY OUT DIAGNOSTIC CHECK. S/N \$	292.00 ✓	
TOTAL LABOUR CHARGES		: \$ 12,032.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 790 E

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT DOOR - RH	1	\$ 3,977.00	ba ✓
2	FRONT OUTER DOOR SEAL - RH	1	\$ 247.00	nei ✓
3	BONDING AGENT	1	\$ 51.00	nei ✓
4	CLEANING SOLUTION	1	\$ 74.00	nei ✓
5	APPLICATOR	1	\$ 9.00	nei ✓
6	FRONT DOOR CATCH - RH	1	\$ 134.00	X
7	FRONT DOOR CHROME TRIM - RH	1	\$ 171.00	X
8	FRONT TYRE PRESSURE DATA PLATE	1	\$ 41.00	nei ✓
9	REAR DOOR - RH	1	\$ 3,977.00	bt ✓
10	REAR OUTER DOOR SEAL - RH	1	\$ 247.00	nei ✓
11	BONDING AGENT	1	\$ 51.00	nei ✓
12	CLEANING SOLUTION	1	\$ 74.00	nei ?
13	APPLICATOR	1	\$ 9.00	?
14	REAR DOOR CATCH - RH	1	\$ 134.00	X
15	REAR DOOR SIDE MEMBER TRIM - RH	1	\$ 872.00	Ry
16	REAR ATTACHMENT PARTS	1	\$ 136.00	nei ✓
17	ADHESIVE TAPES	1	\$ 221.00	nei ✓
18	REAR ALUMINIUM RIM	1	\$ 1,889.00	cut ✓
19	REAR ALUMINIUM RIM RUBBER VALVE	1	\$ 4.00	nei ✓
20	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 12,818.00	
TOTAL LABOUR CHARGES		:	\$ 12,032.00	
GRAND TOTAL		:	\$ 24,850.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Taufiq 97445749 / 67563561
 SURVEYED DATE : 01/17/2018 1115
 AUTHORISED DATE :
 EXCESS COST : Not Authorised Ex: to be advise
 LIABILITY : Resurvey before paint
 REMARKS : Taufiq @ khairat.com
 8 days

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT