

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LIBERTY INSURA	NCE PTE LTD	Re	ef:	CS3/LIP22012084/y3
	51 CLUB STREET, LIBERTY HOUSES	#03-00 SINGAPORE 069428	Da	ate:	02/12/2022
			Co	ode:	LIP
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SNC 3117X	Veh. Inspected		SKX 8214R
	Policy No.		Coverage (\$)		0.00
	Claim No.	IVS22/2058	Excess (\$)		0.00
	Assign From	TED SEAH	Assign Date		02/12/2022
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	Year of Reg.			
	Chassis No.	Colour			
	Odometer -		Steering		
	Brakes	Modification			
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	General Information				
	Accident Date	27/11/2022	Inspection Date		
	Survey held at	LEE LUEW SING MOTORS			
		NO 10 ANG MO KIO INDUSTRIAL PARK 2A #03-10 AMK AUTOPOINT SINGAPORE 568047			
5a.	. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				