

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 7 December 2022 11:34 AM  
**To:** YT(HQ); SUR  
**Cc:** info@yewteegroup.com; 'YTKB'  
**Subject:** RE: SLH 3410X-DOA: 29/11/2022 (ECICS OD)

Dear Shaun,

As instructed by our client , please proceed to repair the **insured vehicle SLH 3410X. Part by part repair. (Excess \$0-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Please provides parts invoice upon finalize

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** YT(HQ) <utauto@singnet.com.sg>  
**Sent:** Tuesday, 6 December 2022 12:01 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Cc:** info@yewteegroup.com; 'YTHQ' <utauto@singnet.com.sg>; 'YTKB' <utauto2@singnet.com.sg>  
**Subject:** RE: SLH 3410X-DOA: 29/11/2022 (ECICS OD)  
**Importance:** High

Hi Veron

We have check and there is totally no used parts in the market for this vehicle

Hence if offer on lump sum repair

example

Frt door \$550.00 + 10% less 20% = \$484.00

hence is already below our cost to purchase the parts

can u pls advise officer on it. How to go about?

Thanks

Best Regards  
Shaun Toh L M



Business account WhatsApp: 6702 3323

Website: [www.yewteegroup.com](http://www.yewteegroup.com)

Like Us On Facebook & Instagram

Senior Manager of

**-YEW TEE AUTOMOBILE TECH PTE LTD**

**-YEW TEE (CAMBODIA) AUTOMOBILE CO. LTD**

**-SE OPULENCE GROUP**

**-ARUKORU BAR**

Branch Office:

Synergy@KB, [25 Kaki Bukit Road 4](#)

Unit No #01-60

Singapore 417800

DID: [6702 3113](#)

Fax: [6702 3773](#)

Email: [info@yewteegroup.com](mailto:info@yewteegroup.com)

*P please consider the environment before printing this email*

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person

---

**From:** Veron Chen (LKKAUTO) <[veronchen@lkkauto.com](mailto:veronchen@lkkauto.com)>

**Sent:** Tuesday, December 6, 2022 8:08 AM

**To:** YT(HQ) <[utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

**Subject:** SLH 3410X-DOA: 29/11/2022 (ECICS OD)

Dear Sir,

As instructed by our client , please proceed to repair the **insured vehicle SLH 3410X. Lump Sum Repair. (Excess \$0-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)