



**SERVICE ESTIMATE**

##### - C00001 SL: SERVICE SALES - PC  
 Mr Wong Kwok Kwong  
 10 Old Upper Thomson Road  
 #02-06  
 Singapore 573869

GST Reg.No:M28920628X  
 Inv.No. . : B&P 0 Page 1  
 Inv.date. : 01/12/2022  
 WIP No. . : 52668  
 Veh.In/Out:  
 \*Tel.No. . : Mobile: 83999159  
 Reg.No. . : SNB3995H  
 Reg.date .: 19/08/2021  
 Mileage ..: 0  
 Chassis No: LYVXZAKADML585891

Closed by .... : Michelle Ong Siew Be  
 Svc Consultant :  
 Remarks ..... : Mr Wong Kwok Kwong

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER, FRONT LOWER BUMPER, RHF FENDER WIDENER, BRACKETS, CLIPS, ETC.	0	1700.00	0		1,700.00	S 850/
800	TO BLEND AND SPRAY PAINT ON FRONT BUMPER, ETC.	0	1500.00	0		1,500.00	S 750/
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	588.00	0		588.00	S //
	V039790879/BUMPER CO	1.0 EA	2309.70			2,309.70	S 2078.73
	BUMPER SPOILER FRT A	1.0 EA	590.40			590.40	S 531.36
	WHEEL AIR DEFLECTOR	1.0 EA	81.20			81.20	S X
	WIDENER FRT RH XC40	1.0 EA	202.90			202.90	S 182.61
	BUMPER INSTALLING MT	1.0 EA	101.40			101.40	S 91.26
	BUMPER CLIP XC90 16-	10.0 EA	8.80			88.00	S 79.20
	BLIND RIVET 4.0*21 P	10.0 EA	5.00	20		50.00	S 46.80
	BUMPER CLIP 8x8,5	10.0 EA	8.20			82.00	S 73.80
	BUMPER CLIP GREEN S6	10.0 EA	6.00			60.00	S 54.00

**SERVICE ESTIMATE**

##### - C00001 SL: SERVICE SALES - PC

Mr Wong Kwok Kwong  
10 Old Upper Thomson Road  
#02-06

Singapore 573869

Closed by .... : Michelle Ong Siew Be  
Svc Consultant :  
Remarks ..... : Mr Wong Kwok Kwong

GST Reg.No:M28920628X  
Inv.No. . : B&P 0 Page 2  
Inv.date. : 01/12/2022  
WIP No. . : 52668  
Veh.In/Out:  
\*Tel.No. . : Mobile: 83999159  
Reg.No. . : SNB3995H  
Reg.date . : 19/08/2021  
Mileage .. : 0  
Chassis No: LYVXZAKADML585891

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	EXPANDING NUT XC40 1 <i>Rec</i>	10.0 EA	6.70	90		67.00	S 62.10

*Rasa*  
*Hp 9000018*  
*3 days*  
*13/12/22 @ 1130*  
*Resy before pick*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

		Gross Total.	7,420.60
Labour Total	3,788.00	Net.....	7,420.60
Parts Total	3,632.60	GST @ 7.0%	519.44
Package Total	0.00	Total.....	7,940.05
		Paid.....	0.00
		Please Pay..	7,940.05

GST: S=StdRated; O=OutOfScope; Z=ZeroRated