



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Ref: CS3/ASM22012107/Rvp3

Date: 02/12/2022

Code: ASM

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

|                     |             |                       |            |
|---------------------|-------------|-----------------------|------------|
| <b>Insured Veh.</b> | SHA 4729E   | <b>Veh. Inspected</b> | GBA 7108Z  |
| <b>Policy No.</b>   |             | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | S2M04FR6    | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | LOH CYNTHIA | <b>Assign Date</b>    | 02/12/2022 |

**2. Vehicle Particulars & Condition**

|                         |        |                     |   |
|-------------------------|--------|---------------------|---|
| <b>Make &amp; Model</b> |        | <b>c.c</b>          | 0 |
| <b>Engine No.</b>       | HIDDEN | <b>Year of Reg.</b> |   |
| <b>Chassis No.</b>      |        | <b>Colour</b>       |   |
| <b>Odometer</b>         | -      | <b>Steering</b>     |   |
| <b>Brakes</b>           |        | <b>Modification</b> |   |
| <b>General</b>          |        |                     |   |

**3. Conditions of Tyres**

|                       | Size | Make | Balance |
|-----------------------|------|------|---------|
| <b>R/H Front Tyre</b> |      |      | mm      |
| <b>L/H Front Tyre</b> |      |      | mm      |
| <b>R/H Rear Tyre</b>  |      |      | mm      |
| <b>L/H Rear Tyre</b>  |      |      | mm      |

**4. Description of Damages**

|  |  |
|--|--|
|  |  |
|--|--|

**5. General Information**

|                       |                                                    |                        |            |
|-----------------------|----------------------------------------------------|------------------------|------------|
| <b>Accident Date</b>  | 30/11/2022                                         | <b>Inspection Date</b> | 05/12/2022 |
| <b>Survey held at</b> | 5 Soon Lee Street #06-36 Pioneer Point Singapore 6 |                        |            |
| <b>Repairer</b>       | TAI TIONG AUTO MOBIL TRADING                       |                        |            |

**5a. Remarks**

|                                                                                                                                                                                                                                                  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|