

**Borneo Motors**

inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA**

TP/PI Finalize
ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	Mdm Arianty Hartawan 747C Bedok Reservoir Crescent #10-25 Singapore 473747 Mobile: 91559431
	Document No. 0	
	Document Date 27/12/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZGE20R	HPXNP S4	11/03/2015	SKR8254G	0	22211	69DS/SKR8254G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W70J002221	2ZR1517666	60	Raymond Seah L M	19/12/2022 10.15	27/12/2022 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH:SHB5885A ACC DATE:01/12/2022 TP INS:FIRST CAPITAL NO OF REPAIR DAYS:07 DATE-IN:17/12/2022 DATE SURVEY:19/12/2022 BY:LKK-MARCUS AUTHORISED ON:06/12/2022 -TP/DS CLAIM				30.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR TAILGATE AND REAR END PANEL.				120.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
4	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.	BP09			134.64
5	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.	BP09			198.00
6	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.	0741			400.00
7	B	BP-WS2 R/I REAR WINDSCREEN TO FACILIATE REPAIRS.	BP09			594.00
8	B	BP-LAB2 R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILIATE REPAIRS.	BP09			396.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	Amount Due
		Others	

Company Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	Mdm Arianty Hartawan 747C Bedok Reservoir Crescent #10-25 Singapore 473747 Mobile: 91559431
	Document No. 0	
	Document Date 27/12/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZGE20R	HPXNP S4	11/03/2015	SKR8254G	0	22211	69DS/SKR8254G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W70J002221	2ZR1517666	60	Raymond Seah L M	19/12/2022 10.15	27/12/2022 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB2 TO TRANSFER REAR TAILGATE BOARD, MOTOR, REAR CAMERA, TOP SPOILER AND OTHER ATTACHMENT TO FACILITATE REPAIRS. BP09				396.00
10	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS. BP09				3168.00
11	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS. *				1968.00
12	1	T89997-30070 ANTENNA, ELECTRICAL	1.00	228.90		228.90
13	2	T52159-68907 PLATE, RR BUMPER	1.00	703.60		703.60
14	3	S52161-0K040 PIECE, RR BUMPER	10.00	4.90		49.00
15	4	T52575-68020 RETAINER, RR BUMPER	1.00	54.70		54.70
16	5	T52576-68020 RETAINER, RR BUMPER	1.00	54.70		54.70
17	6	T52155-68030 SUPPORT, RR BUMPER	1.00	116.10		116.10
18	7	T52156-68030 SUPPORT, RR BUMPER	1.00	116.10		116.10
19	8	T58307-68031 PANEL SUB-ASSY, BODY	1.00	638.90		638.90
20	9	T67935-68020 B0 PLATE, BACK DOOR	1.00	355.00		355.00
21	0	T68105-68071 GLASS SUB-ASSY, BACK	1.00	1267.40		1267.40
22	1	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00
23	2	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
24	3	T67005-68041 PANEL SUB-ASSY, BACK	1.00	1759.30		1759.30

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Company Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1	Mdm Arianty Hartawan 747C Bedok Reservoir Crescent #10-25 Singapore 473747 Mobile: 91559431
	Document No. 0	
	Document Date 27/12/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZGE20R	HPXNP S4	11/03/2015	SKR8254G	0	22211	69DS/SKR8254G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDGG20W70J002221	2ZR1517666	60	Raymond Seah L M	19/12/2022 10.15	27/12/2022 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
25	4	T67881-68030 WEATHERSTRIP, BACK	1.00	399.90		399.90
26	5	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20
27	6	T75444-68010 PLATE, LUGGAGE COMPT	1.00	48.90		48.90
28	7	T75443-ELGAN ELEGANCE EMBLEM	1.00	40.00		40.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	13,923.34	
	Please acknowledge receipt of vehicle	Parts	6,320.70	GST 7.00%	974.63
		Labour	7,202.64		
		Sublet	400.00	Less	0.00
		Lubrication/Fluid	0.00		
		Others	0.00		
				Amount Due	14,897.97

Company Copy