



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM <i>liability check</i>			S1000020 / TPCLAIM		Mdm Arianty Hartawan 747C Bedok Reservoir Crescent #10-25 Singapore 473747 Mobile: 91559431		
			Document No. 0				
			Document Date 02/12/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZGE20R	HPXNP S4	11/03/2015	SKR8254G	0	22211	69DS/SKR8254G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDGG20W70J002221		2ZR1517666	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES TP VEH:SHB5885A ACC DATE:01/12/2022 TP INS: NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM				30.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR TAILGATE AND REAR END PANEL.				120.00	
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
4	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				134.64	
5	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.				198.00	
6	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.				400.00	
7	B	BP-WS2 R/I REAR WINDSCREEN TO FACILIATE REPAIRS.				594.00	
8	B	BP-LAB2 R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				396.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		Amount Due
					Others		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 17 UBI ROAD 4
 SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mdm Arianty Hartawan 747C Bedok Reservoir Crescent #10-25 Singapore 473747 Mobile: 91559431
	Document No. 0	
	Document Date 02/12/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZGE20R	HPXNP S4	11/03/2015	SKR8254G	0	22211	69DS/SKR8254G
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDGG20W70J002221	2ZR1517666	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB2 TO TRANSFER REAR TAILGATE BOARD, MOTOR, REAR CAMERA, TOP SPOILER AND OTHER ATTACHMENT TO FACILITATE REPAIRS.				396.00
10	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				4752.00
11	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.				3936.00
12	1	SPZ061-12010 25 202 SENSOR	1.00	151.60		151.60
13	2	T89997-30070 ANTENNA, ELECTRICAL	1.00	228.90		228.90
14	3	T81910-13022 REFLECTOR ASSY,	1.00	71.40		71.40
15	4	T81920-13022 REFLECTOR ASSY,	1.00	71.40		71.40
16	5	T52159-68907 PLATE, RR BUMPER	1.00	703.60		703.60
17	6	S52161-0K040 PIECE, RR BUMPER	4.00	4.90		19.60
18	7	T52575-68020 RETAINER, RR BUMPER	1.00	54.70		54.70
19	8	T52576-68020 RETAINER, RR BUMPER	1.00	54.70		54.70
20	9	T52155-68030 SUPPORT, RR BUMPER	1.00	116.10		116.10
21	0	T52156-68030 SUPPORT, RR BUMPER	1.00	116.10		116.10
22	1	T58307-68031 PANEL SUB-ASSY, BODY	1.00	638.90		638.90
23	2	T67935-68020 B0 PLATE, BACK DOOR	1.00	355.00		355.00
24	3	T68105-68071 GLASS SUB-ASSY, BACK	1.00	1267.40		1267.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mdm Arianty Hartawan 747C Bedok Reservoir Crescent #10-25 Singapore 473747 Mobile: 91559431
	Document No. 0	
	Document Date 02/12/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2015	ZGE20R	HPXNP S4	11/03/2015	SKR8254G	0	22211	69DS/SKR8254G
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDGG20W70J002221	2ZR1517666	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
25	4	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00
26	5	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00
27	6	T67005-68041 PANEL SUB-ASSY, BACK	1.00	1759.30		1759.30
28	7	T67881-68030 WEATHERSTRIP, BACK	1.00	399.90		399.90
29	8	T69350-28151 LOCK ASSY, BACK DOOR	1.00	490.90		490.90
30	9	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20
31	0	T75444-68010 PLATE, LUGGAGE COMPT	1.00	48.90		48.90
32	1	T75443-ELGAN ELEGANCE EMBLEM	1.00	40.00		40.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary		Total	18,231.24
	Please acknowledge receipt of vehicle	Parts	7,076.60	GST 7.00%	1,276.19
		Labour	10,754.64		
		Sublet	400.00	Less	0.00
		Lubrication/Fluid	0.00		
		Others	0.00		
				Amount Due	19,507.43

Customer Copy