



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd	
		Document No. 0		3 Media Close #01-03/06 Singapore 138498	
		Document Date 01/12/2022		Work: 65703925	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ Q3	17/10/2016	SLG8769J	0	18890	66TP/SLG8769J/301122
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		

MR053REH104558000	1ZRY332131	60	Shashitharan	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	--------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: SHF185Z ACC DATE: 30/11/22 DRIVE IN: 30/11/22 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON: 2 BP-MECH2 RESET ECU UPON COMPLETION OF REPAIR 3 BP-MECH2 CONDUCT WHEEL ALIGNMENT 4 BP-MECH2 REPL LH FRT UNDERCARRIAGE PART 5 BP-MECH2 REPL REAR LH UNDERCARRIAGE PART 6 S BP-SUBLET TRANSFER FRT AND REAR TYRE TO NEW RIM 7 Z BP-SLANT SUPPLY SEALANT (NETT) 8 BP-LAB2 TRANSFER RH FRT AND REAR DOOR MECHANISM 9 BP-LAB2 REPL ACC AFF PARTS AND PANEL C 142 10 BP-RES2 RESRPAY ACC AFF AREA C 157 11 1 K52116-02270 SUPPORT, FR BUMPER S 12 2 K52119-02955 COVER, FR BUMPER L/C de 13 3 K53802-02220 FENDER SUB-ASSY, FR de 14 4 K53876-02680 LINER, FR FENDER, LH de 15 5 K61602-02280 PANEL SUB-ASSY, QUAR de repair				50	100.00
						198.00	
						198.00	
						792.00	
						792.00	
						160.00	
						200.00	
						792.00	
						3168.00	
						3608	
			1.00	101.70		101.70	
			1.00	633.80		633.80	
			1.00	1081.20		1081.20	
			1.00	270.50		270.50	
			1.00	1369.30		1369.30	

For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
						Amount Due	

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. : 6631 1188

ESTIMATE

Account Details				Account No.		Customer Details	
THIRD PARTY CLAIM				S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd	
				Document No.		3 Media Close	
				0		#01-03/06	
				Document Date		Singapore 138498	
				01/12/2022		Work: 65703925	
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGK Q3	17/10/2016	SLG8769J	0	18890	66TP/SLG8769J/301122
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR053REH104558000	1ZRY332131	60	Shashitharan	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
16	6	PANEL SUB-ASSY, FR D ^{lt}	1.00	1495.20		1495.20	
17	7	TAPE, BLACK OUT, NO. ² lt	1.00	57.20		57.20	
18	8	TAPE, BLACK OUT, NO. ² lt	1.00	51.90		51.90	
19	9	PANEL SUB-ASSY, RR D ^{lt}	1.00	1481.90		1481.90	
20	0	PLATE, LUGGAGE COMPT ² lt	1.00	42.30		42.30	
21	1	HUB & BRG ASSY, RR A ² lt	1.00	1143.90		1143.90	
22	2	WHEEL, DISC ² lt	2.00	2390.80		4781.60	
23	3	SHAFT ASSY, FR DRIVE ² lt	1.00	1486.20		1486.20	
24	4	BEARING, RADIAL BALL ² lt	1.00	129.10		129.10	
25	5	HUB SUB-ASSY, FR AXL ² lt	1.00	311.40		311.40	
26	6	JOINT ASSY, LWR BALL ² lt	1.00	283.60		283.60	
27	7	KNUCKLE, STEERING, L ² lt	1.00	747.30		747.30	
28	8	ARM SUB-ASSY, SUSPEN ² lt	1.00	873.80		873.80	
29	9	ABSORBER SET, SHOCK, ² lt	1.00	523.40		523.40	
<i>Panel</i> <i>4p 20110068</i> <i>8 days</i> <i>05/12/22 21410</i> <i>Resy before print</i>							
Charge Summary			Total				
Parts			16,865.30				
Labour			10,176.00				
Sublet			160.00				
Lubrication/Fluid			0.00				
Others			0.00				
Total			27,201.30				
GST 7.00%			1,904.09				
Less			0.00				
Amount Due			29,105.39				

LKK Auto Consultants hence notify

the Repairer of the following:

For & on behalf of the repairer before resurvey spray painting

To display damaged part(s) during resurvey

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer's Signature

Customer Copy



Reg No. : 196700086Z
T Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

Reg No. : 196700086Z

T Reg No. : MR-8500000.9

2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

Supplementary

ESTIMATE

Account Details				Account No.		Customer Details	
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept				S100005 / ICFIC1		M/S Grab Rentals Pte Ltd	
				Document No. 0		3 Media Close #01-03/06 Singapore 138498	
				Document Date 14/12/2022		Work: 65703925	
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ Q3	17/10/2016	SLG8769J	0	18890	66TP/SLG8769J/301122
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053REH104558000		1ZRY332131	60	Shashitharan	06/12/2022 8.00		14/12/2022 18.00
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
1		HEADLAMP ASSY, LH		1.00	1105.20		1105.20
2		PROTECTOR, FR FENDER		1.00	119.50		119.50
For & on behalf of Borneo Motors (Singapore) Pte Ltd				Customer's Signature		Total	
Please acknowledge receipt of vehicle				Parts		1,224.70	
				Labour		0.00	
				Sublet		0.00	
				Lubrication/Fluid		0.00	
				Others		0.00	
				GST 7.00%		85.73	
				Less		0.00	
				Amount Due		1,310.43	

Company Copy