

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation Non binding - Preview

Page 1/2

Document no. 02-12-2022
Document date 5211043801
Customer no. 30001
Customer GST-ID 2022035308/ 1
Dealer Job order number 02-12-2022
Job order date YEN MEI WONG
Service Advisor

Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Customer Details:
Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

License plate	Model code	First registration	VIN	Model	Mileage
SNF5873S	C113KZR1	07-06-2022	WVGZZC1ZNY079015	T-Cross R-Line 1.0 I TSI 85kW DSG	18

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	480.00	513.60
2GM807421 GRU	Cover For Bumper Primed REAR BUMPER (UPPER)	1	pcs.	1,280.79	#1	1,280.79	1,370.45
2GM919397 GRU	Sensor Bracket Primed	1	pcs.	14.79	#1	14.79	15.83
2GM919398 GRU	Sensor Bracket Primed	1	pcs.	14.79	#1	14.79	15.83
2GM919491	Sensor Bracket	1	pcs.	12.92	#1	12.92	13.82
2GM919492	Sensor Bracket	1	pcs.	12.92	#1	12.92	13.82
2GM919491A	Sensor Bracket	2	pcs.	12.92	#1	25.84	27.65
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	#1	68.85	73.67
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	#1	85.94	91.96
2GM807521B GRU	Spoiler Primed REAR BUMPER (CTR)	1	pcs.	320.09	#1	320.09	342.50
2GM807568A 9B9	Rear Diffuser Satin Black REAR BUMPER (LOWER)	1	pcs.	249.00	#1	249.00	266.43
2GM807305	Bumper Bracket REINFORCEMENT	1	pcs.	709.97	#1	709.97	759.67
2GM807863A	Attachment Strip BUMPER CTR BRACKET	1	pcs.	70.05	#1	70.05	74.95
2GM807393P	Guide Piece LHR BUMPER BRACKET (UPPER)	1	pcs.	42.59	#1	42.59	45.57
2GM807394P	Guide Piece RHR BUMPER BRACKET (UPPER)	1	pcs.	42.59	#1	42.59	45.57
2GM807393M	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	40.20	#1	40.20	43.01
2GM807394M	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	40.20	#1	40.20	43.01
2GM945701A	Reflector LH	1	pcs.	81.02	#1	81.02	86.69
	LABOUR	21	pcs.	840.00	#1	2,520.00	2,696.40
	SPRAY PAINT MSIG VS LONPAC 3RD PARTY VEHICLE SMR3968P D.O.A: 01-12-2022 SURVEY BY:		pcs.	840.00	#1	3,360.00	3,595.20

Quotation valid till 09-12-2022

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	8,992.55	7%	682.68	9,752.55	10,435.23
Total	760.00	8,992.55		682.68	9,752.55	10,435.23

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page	2/2
Document no.	
Document date	02-12-2022
Customer no.	5211043801
Customer GST-ID	
Dealer	30001
Job order number	2022035308/ 1
Job order date	02-12-2022
Service Advisor	YEN MEI WONG

Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

Customer Details:
Company
Lonpac Insurance BHD
101 Thomson Road
#18-01 United Square
Singapore 307591

License plate	Model code	First registration	VIN	Model	Mileage
SNF5873S	C113KZR1	07-06-2022	WVGZZZC1ZNY079015	T-Cross R-Line 1.0 TSI 85kW DSG	18

Customer



—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

All invoices are denominated in SGD, unless otherwise stated.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rame
HP 90010068
3 days
07/12/22 @ 1550
Rem before paint