

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 09 Dec 2022

Preliminary Advice

Vehicle No	: SMG9917E	Accident Date	: 01/12/2022
Make	: OPEL INSIGNIA GRANDSPORT B16DTH	Policy No.	: SP2002451400
Assignment Date	: 03/12/2022	Excess	: S\$2,000.00
Date of Inspection	: 09/12/2022	Est. Duration of Repair	: 4
Inspection At	: MUNICH AUTOCARE PTE LTD (HQ) 60 JALAN LAM HUAT, #07-43 SINGAPORE 737869		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,625.30
Revised Amount	:S\$	7,126.80
Check Items (Estimated)	:S\$	2,341.90
Total	:S\$	9,468.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	41,354.00
Salvage Value	:S\$	
Margin for Repair	:S\$	48,646.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.